

BUICK REAR COMPARTMENT LOCKS

General information as follows:

1. For applications before 1967 (B10 & B11 keys) see the separate section.
2. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
3. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
4. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Apollo	1973-75	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Centurion	1971-73	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1971-73 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Century except station wagon	1973-96	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Century wagon	1973-77	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Century wagon	1984-96	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Century	1997-05	B86			Use face cap RP6036 (P-41-201) Use tumbler series P-41-161/164		
Electra	1967-68	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Electra	1969-70	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Electra	1971	GMA/K	Uncoded plug	B-41-301	Use tumbler series P-41-101/105		
Electra	1972-90	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1972-76 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Enclave	2008-17	B111	Replacement locks available from Strattec				
Enclave	2018-19	HU100	Replacement locks available from Strattec				
Estate Wagon	1968-70	GMA/K	Uncoded service pack	DL1580U	Coded lock (available as a pair only)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Estate Wagon	1971-76	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Estate Wagon	1977-91	GMA/K	Uncoded service pack	DL1580U	Coded lock (available as a pair only)	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Le Sabre	1967-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1971-76 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Le Sabre	1992-94	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Le Sabre	1995-99	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Le Sabre	2000-05	B97	Uncoded service pack	B-41-001	Use tumbler series P-41-121/124		
Lucerne	2006-07	B111	Replacement locks available from Strattec				
Opel Isuzu (Japanese)	1976-79	DC1	Complete lock	B-24-102	Use tumbler series P-30-141/144		

Scroll down for more

BUICK REAR COMPARTMENT LOCKS

Park Avenue	1989-96	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Park Avenue	1997-05	B99	Replacement locks available from Buick / GM dealers only. Use tumbler series P-41-111/114				
Reatta	1988-92	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Regal except station wagon	1973-97	GMA/K	Uncoded service pack chrome	TL1575U	Coded lock chrome	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Regal station wagon	1978-83	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Regal	1997-04	B85	Use face cap RP6036 (P-41-201) Use tumbler series P-41-161/164				
Rendezvous	2002-07	B99	Replacement locks available from Buick / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114				
Riviera	1967-70	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Riviera	1971-72	GMA/K	Uncoded plug	B-41-301	Use tumbler series P-41-101/105		
Riviera	1973-93	GMA/K	Uncoded service pack chrome	TL1575U	Coded lock chrome	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Riviera	1995-99	B85	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Roadmaster	1992-96	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Roadmaster station wagon	1992-96	GMA/K	Replacement locks available from Strattec Use tumbler series P-41-101/105				
Skyhawk	1975-80	GMA/K	Uncoded plug	B-41-301	Use face cap P-41-216 Use tumbler series P-41-101/105 To rebuild the original lock use the original lock housing with a new plug B-41-301, dust cover RP6508, and face cap P-41-216. New lock housings are no longer available.		
Skyhawk exc. station wagon	1982-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Skyhawk station wagon	1982-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Skylark	1967-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Skylark	1992-94	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Skylark	1995-99	B85	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Somerset	All		see Skylark				
Terraza	2005-07	B111 or B86	Locks using B111 keys, available from Buick / GM dealers only. Use tumbler series P-41-011/015				
			Locks using B86 keys, available from Strattec Use tumbler series P-41-161/164				
Wildcat	1967-70	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105

Scroll down for tumbler and keying kit information

BUICK REAR COMPARTMENT LOCKS

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

To help avoid confusion, whenever possible the year and model section includes which tumbler series to use in the notes section.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO) Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.
B85, B89, B97, B99 Locks made by Ortech sold by ASP	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B85, B89, B97, B99 Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B102, B107, B111 Locks made by Ortech sold by ASP	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
DC1, DC3	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
HU100	P-23-121 (1R)	P-23-122 (2R)	P-23-123 (3R)	P-23-124 (4R)		A-23-103 current keying kit
	P-23-131 (1L)	P-23-132 (2L)	P-23-133 (3L)	P-23-134 (4L)		

Scroll down for information about tumbler springs

BUICK REAR COMPARTMENT LOCKS

Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. RP6037 (P-41-100)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using HU100 2-track high security keys - part no. P-31-100

For locks using DC1 keys, can also be substituted to use in locks using double bitted keys B97, etc.: P-00-100 - currently active part number - 100 springs per pack

Part numbers previously used, now superseded to P-00-100

P-16-105 P-30-108

P-19-100 RP6546

P-20-105 RP6612

P-20-115 RP6731

P-24-105 RP6822

P-30-105