

BUICK DOOR LOCKS

See the separate section for Buick before 1967 model year.

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
3. Unless specified otherwise pawls are not included with replacement locks, the original pawls must be reused.
4. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Allure	2005-09	B111	Coded lock	D-41-006			
Allure	2010-15	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Apollo	1973-75	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Cascada	2016-20	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Centurion 2-door	1971	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Centurion 4-door	1971	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Centurion	1972-73	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Century	1973-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Century 2-door	1979-81	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Century 4-door and wagon	1979-96	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Century	1997-05	B85	Replacement locks available from Strattec				
Electra	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Electra 2-door	1971	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Electra 4-door	1971	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Electra	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Electra	1977-90	GMA/K	Uncoded service pack no alarm, non lighted chrome	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack no alarm, non lighted black	DL1525U	Coded pair	DL1525	Use face cap RP6520 (P-41-202)
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			With lighted keyhole – replacement locks available from Strattec				

Scroll down for more

BUICK DOOR LOCKS

Enclave	2008-17	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Enclave	2018-24	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Encore	2013-22	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Envision	2016-24	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Estate Wagon	All		see Le Sabre (4-door)				
La Crosse	2005-09	B111	Coded lock	D-41-006			
La Crosse	2010-16	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
La Crosse	2017-21	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Le Sabre	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Le Sabre 2-door	1971	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Le Sabre 4-door	1971	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Le Sabre	1972-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Le Sabre	1977-99	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1977, 1981, and 1991-99 models only. Uncoded service package not available with other keyways as used 1978-80 and 1982-90. Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			With lighted keyhole – replacement locks available from Strattec				
Le Sabre	2000-05	B99	Uncoded service pack	D-41-005	Use face cap P-41-205 Use tumbler series P-41-121/124 for D-41-001 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers.		
Lucerne	2006-11	B111	Coded lock	D-41-006			
Opel Isuzu (Japanese)	1976-79	DC1	Uncoded service pack	D-24-201	Use face cap P-24-203 (chrome) or P-24-204 (black) Use tumbler series P-30-141/144		
Park Avenue	1989-96	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1991-96 models only. Uncoded service package not available with other keyways as used 1989-90 Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			With lighted keyhole – replacement locks available from Strattec				
Park Avenue	1997-05	B99	Replacement locks available from Buick / GM dealers only. Parts to service original locks are available as follows: Face cap: P-41-203, Dust cover assembly: P-41-233 Plastic pawls (1997-99 only): P-41-301 for right side, P-41-302 for left side Use tumbler series P-41-111/114				
Rainier	2004-07	B99	Replacement locks available from Strattec				
Reatta	1988-92	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1991-92 models only. Uncoded service package not available with other keyways as used 1988-90 Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			With lighted keyhole – replacement locks available from Strattec				
Regal	1973-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)

Scroll down for more

BUICK DOOR LOCKS

Regal 2-door	1979-87	GMA/K	Uncoded service pack (chrome) for cars without factory alarm	DL1582U	Coded pair (chrome) for cars without factory alarm	DL1582	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black) for cars without factory alarm	DL1527U	Coded pair (black) for cars without factory alarm	DL1527	Use face cap RP6520 (P-41-202)
			Coded pair for cars with factory alarm (chrome only)	DP-41-115	Use face cap chrome RP6036 (P-41-201), or black RP6520 (P-41-202) DP-42-115 is only available in chrome with random keyway, for black trim replace the chrome face caps and dust covers with black equivalents. Use tumbler series P-41-101/105		
Regal 2-door	1988-97	GMA/K	Uncoded service pack	DL1508U (DWO)	Coded pair	DL1508	
Regal 4-door	1973-87	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Regal 4-door	1988-97	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202)
Regal	1997-05	B85	Replacement locks available from Strattec				
Regal	2011-17	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Regal	2018-20	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Rendezvous	2002-07	B99	Replacement locks available from Buick / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114				
Riviera	1967-70	GMA/K	Uncoded service pack	D-41-221	Coded pair	DL1581	Use face cap RP6036 (P-41-201)
Riviera	1971-74	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Riviera	1975-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Riviera	1977-80	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Riviera	1981-85	GMA/K	Uncoded service pack no alarm, non lighted	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			With lighted keyhole – replacement locks available from Strattec				
Riviera	1986-93	GMA/K	Uncoded service pack no alarm, non lighted, chrome	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack no alarm, non lighted black	DL1525U	Coded pair	DL1525	Use face cap RP6520 (P-41-202)
			Coded pair with factory alarm no lighted keyhole chrome	DP-41-115			
			Uncoded service pack with factory alarm no lighted keyhole chrome	D-41-215	NOTE: D-41-215 uses H keyway used on 1991-93 models only. Uncoded service package not available with other keyways as used 1986-90 Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105		
			Uncoded service pack with factory alarm no lighted keyhole black	D-41-242	NOTE: D-41-242 uses H keyway used on 1991-93 models only. Uncoded service package not available with other keyways as used 1986-90 Use face cap RP6520 (P-41-202) Use tumbler series P-41-101/105		
			With lighted keyhole – replacement locks available from Strattec				
Riviera	1995-99	B85	Replacement locks available from Strattec				
Roadmaster	1992-96	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Skyhawk	1975-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Skylark	1967-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Skylark	1992-94	GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)	
			Plugs are available as follows Uncoded plug for locks without alarm, unrestricted keyway accepts all GMA through GMK - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315				
Skylark	1995-99	B89	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Special	1967-69	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Somerset	1985-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)

Scroll down for more

BUICK DOOR LOCKS

Terraza	2005-07	B107 or B97	Locks using B107 keys, replacement locks available from Buick / GM dealers only.				
			Locks using B97 keys, available from Strattec Use tumbler series P-41-161/164				
Verano	2012-17	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Verano	2012-17	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Wildcat	1968-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

The tumbler series used for each specific year and model application is listed in the notes section of the main lock application chart.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO) Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.
B99 Locks made by Ortech sold by ASP	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B99 Door Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B102, B107, B111 Ortech Relay C-41-006	P-41-001	P-41-002	P-41-003	P-41-004	P-41-005	Contained in keying kit A-41-152 which is no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Ortech C-41-005	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
DC1	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
HU100	P-23-121 (1R)	P-23-122 (2R)	P-23-123 (3R)	P-23-124 (4R)		A-23-103 current keying kit
	P-23-131 (1L)	P-23-132 (2L)	P-23-133 (3L)	P-23-134 (4L)		

Scroll down for information about tumbler springs

BUICK DOOR LOCKS

Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (Previously RP6157 or RP6043)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using HU100 2-track high security keys - part no. P-31-100

For locks using DC1 keys,

P-00-100 - currently active part number - 100 springs per pack

This spring can also be substituted to use in locks using double bitted keys B97, etc.:

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
P-30-105	