

# BUICK REAR COMPARTMENT LOCKS

See the separate section for Buick before 1967 model year.

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
3. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Apollo	1973-75	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Centurion	1971-73	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1971-73 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Century except station wagon	1973-96	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Century wagon	1973-77	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201)
Century wagon	1978-83	GMA/K	Coded lock	TL1574	NOTE: Some parts from the old lock may need to be reused. Also TL1574 is available in black trim only, chrome locks are no longer available.		
Century wagon	1984-96	GMA/K	Replacement locks available from Strattec				
Century	1997-05	B86	Coded lock	B-41-260	Use face cap RP6036 (P-41-201)		
Electra	1967-68	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Electra	1969-70	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201)
Electra	1971	GMA/K	Coded lock	B-41-251	Available by special request only		
Electra	1972-90	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1972-76 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Enclave	2008-17	B111	Replacement locks available from Strattec				
Enclave	2018-19	HU100	Replacement locks available from Strattec				
Estate Wagon	1970	GMA/K	Uncoded plug Manual tailgate only	B-41-302	Use tumbler series P-41-101/105 Replacement locks for cars with electric tailgate are not available		
Estate Wagon	1971-76	GMA/K	Replacement locks available from Strattec				
Estate Wagon	1977-91	GMA/K	Uncoded service pack	DL1580U	Coded lock (available as a pair only)	DL1580	Use face cap RP6036 (P-41-201)
Le Sabre	1967-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
			NOTE: RP6036 (P-41-201) face cap cannot be used for the lock originally installed on the car on some 1971-76 models with emblem flap over the lock cylinder. Replace the complete lock using TL1575U or TL1575.				
Le Sabre	1992-94	GMA/K	Replacement locks available from Strattec				
Le Sabre	1995-99	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Le Sabre	2000-05	B97	Uncoded service pack	B-41-001	Use tumbler series P-41-121/124		
Lucerne	2006-07	B111	Replacement locks available from Strattec				
Opel Isuzu (Japanese)	1976-79	DC1	Complete lock	B-24-102	Use tumbler series P-30-141/144		
Park Avenue	1989-96	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Park Avenue	1997-05	B99	Replacement locks available from Buick / GM dealers only. Use tumbler series P-41-111/114				
Reatta	1988-92	GMA/K	Replacement locks available from Strattec				
Regal except station wagon	1973-97	GMA/K	Uncoded service pack Chrome	TL1575U	Coded lock chrome	TL1575	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	
Regal wagon	1978-83	GMA/K	Coded lock	TL1574	NOTE: Some parts from the old lock may need to be reused. Also TL1574 is available in black trim only, chrome locks are no longer available.		
Regal	1997-05	B85	Coded lock	B-41-260	Use face cap RP6036 (P-41-201)		

Scroll down for more

# BUICK REAR COMPARTMENT LOCKS

Rendezvous	2002-07	B99	Replacement locks available from Buick / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114				
Riviera	1967-70	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201)
Riviera	1971-72	GMA/K	Coded lock	B-41-251	Available by special request only		
Riviera	1973-93	GMA/K	Uncoded service pack chrome	TL1575U	Coded lock chrome	TL1575	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	TL1523U	Coded lock black	TL1523	
Riviera	1995-99	B85	Replacement locks available from Strattec				
Roadmaster	1992-96	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Roadmaster station wagon	1992-96	GMA/K	Replacement locks available from Strattec				
Special	1967-69	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Skyhawk	1975-80	GMA/K	Coded lock	B-41-215	Use face cap P-41-216		
Skyhawk exc. station wagon	1982-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Skyhawk station wagon	1982-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Skylark	1967-91	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Skylark	1992-94	GMA/K	Uncoded service pack	TL1576U	Coded lock	TL1576	Use face cap RP6036 (P-41-201)
Skylark	1995-99	B85	Replacement locks available from Strattec				
Skylark wagon (Sport Wagon)	1967-72	GMA/K	Uncoded plug Manual tailgate only	B-41-302	Use tumbler series P-41-101/105 Replacement locks for cars with electric tailgate are not available		
Somerset	1985-88	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)
Terraza	2005-07	B111 or B86	Locks using B111 keys, available from Buick / GM dealers only. Use tumbler series P-41-011/015				
			Locks using B86 keys, available from Strattec				
Wildcat	1967-70	GMA/K	Uncoded service pack	TL1575U	Coded lock	TL1575	Use face cap RP6036 (P-41-201)

## Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

To help avoid confusion, whenever possible the year and model section includes which tumbler series to use in the notes section.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO) Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.
B85, B89, B97, B99 Locks made by Ortech sold by ASP	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit  Also contained in keying kit A-41-150 which is no longer available for purchase
B85, B89, B97, B99 Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit  Also contained in keying kit A-41-150 which is no longer available for purchase

Scroll down for more

# BUICK REAR COMPARTMENT LOCKS

B102, B107, B111 Locks made by Ortech sold by ASP	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase.  Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
DC1, DC3	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit  Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
HU100	P-23-121 (1R)	P-23-122 (2R)	P-23-123 (3R)	P-23-124 (4R)		A-23-103 current keying kit
	P-23-131 (1L)	P-23-132 (2L)	P-23-133 (3L)	P-23-134 (4L)		

## Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (Previously RP6157 or RP6043)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using HU100 2-track high security keys - part no. P-31-100

For locks using DC1 keys, can also be substituted to use in locks using double bitted keys B97, etc.: P-00-100 - currently active part number - 100 springs per pack

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
P-30-105	