

CHEVROLET DOOR LOCKS

IMPORTANT: See the separate Chevrolet Trucks section for all years Pickups, Vans, Avalanche, Blazer, Suburban, Tahoe, and other heavy duty trucks.

Also see the separate section for Chevrolet before 1967 model year.

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
3. Unless specified otherwise pawls are not included with replacement locks, the original pawls must be reused.
4. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Chevrolet medium and heavy duty trucks are listed in a separate section at the end of the main section. Pickups and light duty vans are listed in the main section.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Aveo hatchback	2004-11	DWO4R	Complete lock RH Includes pawl	D-50-115	Complete lock LH Includes pawl	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)
Aveo sedan	2004-06	DWO4R	Complete lock RH Includes pawl	D-50-115	Complete lock LH Includes pawl	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)
Aveo sedan	2007-11	DWO4R	Complete lock RH Includes pawl	D-50-117	Complete lock LH Includes pawl	D-50-118	Use tumbler series P-13-101/104 (P-21-111/114)
Bel Air	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Bel Air	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Bel Air	1977-81	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202)
Beretta	1987-96	GMA/K	Replacement locks available from Strattec				
Biscayne	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105
Biscayne	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201) Use tumbler series P-41-101/105

Scroll down for more

CHEVROLET DOOR LOCKS

Bolt	2017-19	HU100			Replacement locks available from Strattec Use tumbler series P-23-121/134		
Camaro	1967-12/69	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Camaro	1/70-78	GMA/K	Uncoded service pack	D-41-221	Coded pair	DL1581	Use face cap RP6036 (P-41-201)
			NOTE: D-41-221 / DL1581 long style door locks are officially the correct locks to use on this model range. Some cars in this range have also been found to use the short door locks (DL1580U / DL1580) or medium door locks (DL1582U / DL1582). To be sure compare the lock that was originally installed on the car, the correct length replacement must be used or the pawl will not fit and function properly.				
Camaro	1979-81	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Camaro	1982-92	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)
Camaro	1993-02	GMA/K	Uncoded service pack (black)	D-41-214	Coded pair (black)	DL6553 (DWO)	Use face cap RP6520 (P-41-202)
			Uncoded service pack (chrome)	D-41-247	Coded pair (chrome)	DL6943	Use face cap RP6036 (P-41-201)
Camaro	2010-15	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Camaro	2016-24	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Caprice	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Caprice	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Caprice	1977-96	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202)
Caprice PPV Police vehicle	2011-13	GM45P	Replacement locks available from GM dealers only Tumblers and service parts are not available.				
Caprice PPV Police vehicle	2014-16	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Captiva	2011-15	B114R	Uncoded service pack LH	D-50-120	Lock service pack includes tumblers and springs for assembly. Tumblers are also available separately P-13-101/104 (P-21-111/114)		
Cavalier	1982-94	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Cavalier	1995-05	B85	Replacement locks available from Strattec Use tumbler series P-41-161/164				
Celebrity	1983-91	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202)
Chevelle	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Chevelle 2-door	1979-81	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Chevelle 4-door & wagon	1979-81	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Chevette	1975-87	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Chevy II	1967-79	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Citation	1978-84	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Cobalt	2005-10	B111	Coded lock	D-41-006			
Corsica	1987 to 1988 mid-year	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)
			Note there was a mid-year change in 1988 from the short plug to the medium plug				
Corsica	Mid-year 1998 To 1996	GMA/K	Uncoded service pack (chrome)	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black)	DL1527U	Coded pair (black)	DL1527	Use face cap RP6520 (P-41-202)
Corvair	1967-69	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Corvette	1967	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Corvette	1968	GMA/K	Push button design lock, no longer available. Try classic Corvette parts specialists.				
Corvette	1969-82	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Coded pair with factory alarm	DP-41-115	Use face cap RP6036 (P-41-201)		
Corvette	1983-90	GMA/K	Coded plugs – keyed alike pair (random keyway)	DP-41-315	Complete lock available from Strattec		
Corvette	1991-96	GMA/K	Uncoded plug (accepts GM-H keyway only)	D-41-302	Coded plugs – keyed alike pair (random keyway)	DP-41-315	Complete lock available from Strattec

Scroll down for more

CHEVROLET DOOR LOCKS

Corvette	1997-04	B85	Replacement locks available from Strattec				
Corvette	2005-19		No lock cylinders, remote control release only				
Cruze	2011-16	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Cruze	2017-23	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
El Camino	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
El Camino	1979-89	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Epica (Canada)	2004-06	DWO5R	Complete lock RH Includes pawl	D-50-121	Complete lock LH Includes pawl	D-50-122	Use tumbler series P-13-101/104 (P-21-111/114)
Equinox	2005-06	B99	Replacement locks available only from Chevrolet / GM dealers Use tumbler series P-41-111/114				
Equinox	2007-09	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Equinox	2010-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Eurosport	1983-91		see Celebrity				
HHR	2006-11	B99	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Impala	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Impala	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Impala	1977-96	GMA/K	Uncoded service pack chrome	DL1580U	Coded pair chrome	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack black	DL1525U	Coded pair black	DL1525	Use face cap RP6520 (P-41-202)
Impala	2000-05	B97	Replacement locks available from Strattec				
Impala LT, Police	2006-16	B111	Replacement locks available from Strattec				
Impala	2014-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Lumina 2-door	1989-94	GMA/K	Uncoded service pack	DL1508U (DWO)	Coded pair	DL1508	
Lumina 4-door	1989-01	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)
Lumina van APV	1990-96	GMA/K	Uncoded service pack without factory alarm or automatic locking 1990-96	D-41-203 (chrome) D-41-249 (black)	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202)		
			Uncoded service pack with factory alarm or automatic locking (1991-96 only)	D-41-216 (chrome) D-41-250 (black)	NOTE: D-41-216 uses H keyway used on 1991-96 models only. Uncoded service package not available with other keyways as used 1990 Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202)		
Malibu	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Malibu 2-door	1979-84	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
Malibu 4-door & wagon	1979-84	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Malibu	1997-03	B97	Replacement locks available from Strattec-4				
Malibu (except Malibu Classic)	2004-12	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Malibu Classic	2004-06	B97	Replacement locks available from Strattec				
Malibu Maxx	2004-07	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Malibu	2013-16	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Malibu	2017-25	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Metro	1995-97	B65	Coded lock (no pawl)	D-33-207	Previously sold as D-33-107 (RH) and D-33-108 (LH) If the original pawl cannot be reused, use P-33-303 (RH) or P-33-304 (LH) Use face cap P-30-217 Use tumbler series P-30-161/164		
Metro	1998-01	B69	Uncoded service pack	D-33-204	Original pawls must be reused. Use face cap P-20-265 Use tumbler series P-20-131/155		
Monte Carlo	1970-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Monte Carlo	1979-89	GMA/K	Uncoded service pack (chrome)	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black)	DL1527U	Coded pair (black)	DL1527	Use face cap RP6520 (P-41-202)

Scroll down for more

CHEVROLET DOOR LOCKS

Monte Carlo	1995-99	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)
Monte Carlo	2000-05	B97	Replacement locks available from Strattec				
Monte Carlo	2006-08	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Monza	1975-80	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Nova	1967-75	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Nova	1984-88	TR33	Lock service package	D-30-206	Coded pair includes pawls	DP-30-106	If original pawl cannot be reused, use P-30-312 (RH) or P-30-313 (LH) Use face cap P-30-271 Use tumbler series P-30-141/144
Optra (Canada)	2004-06	DWO4R	Complete lock RH	D-50-123	Complete lock LH	D-50-124	Use tumbler series P-13-101/104 (P-21-111/114)
Orlando	2012-14	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Prizm	1998-02	TR47 8-cut	Complete lock RH Includes pawl	D-30-171	Complete lock LH Includes pawl	D-30-172	Use face cap P-30-265 Use tumbler series P-30-181/188
Spectrum	1985-91	B53	Uncoded service pack without pawl	D-24-202	Uncoded plug	D-24-302	Use face cap P-30-271 (chrome) or P-30-215 (black) Use tumbler series P-24-101/104
Sprint (Swift)	1985-88	DC1	Complete lock with reversible pawl	D-33-101	Coded pair with pawls	DP-33-101	Use face cap P-24-203 (old part no. P-30-202). Use tumbler series P-30-141/144
Sprint (Swift)	1989-94	B65 (X185)	Uncoded service pack	D-33-205	Previously sold as D-33-105 (RH) and D-33-106 (LH) If original pawl cannot be reused, use P-33-301 (RH) or P-33-302 (LH) Use tumbler series P-30-161/164		
Sonic	2012-20	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Spark	2013-15	DWO4C	Uncoded service pack RH	D-50-125	Uncoded service pack LH	D-50-126	Lock service pack includes tumblers and springs for assembly. Tumblers are also available separately P-13-101/104 (P-21-111/114)
Spark EV	2016	DWO4C	Uncoded service pack RH	D-50-125	Uncoded service pack LH	D-50-126	Lock service pack includes tumblers and springs for assembly. Tumblers are also available separately P-13-101/104 (P-21-111/114)
Spark Except EV	2016-18	HU100	Replacement locks available from GM dealers only Use tumbler series P-23-121/134				
SS	2014-17	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
SSR	All	B99	Replacement locks available from Chevrolet / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114				
Tracker	1999-04	B69	Uncoded service pack	D-33-204	Original pawls must be reused. Use face cap P-20-265 Use tumbler series P-20-131/155		
Trailblazer	2002-09	B97	Replacement locks available from Strattec				
Traverse	2009-17	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		
Traverse	2018-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				
Trax	2015-22	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Uplander	2005-07	B107	Locks using B107 keys, available from Chevrolet / GM dealers only. Use tumbler series P-41-011/015				
		B86	Locks using B86 keys, available from Strattec Use tumbler series P-41-161/164				
Vega	1971-77	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
Venture	1997-05	B97	Replacement locks available from Strattec				
Volt	2011-15	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack Use tumbler series P-23-121/134, contained in kit A-23-103		
Volt	2016-19	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/134				

Scroll down for tumbler and keying kit information

CHEVROLET DOOR LOCKS

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

To help avoid confusion, whenever possible the year and model section includes which tumbler series to use in the notes section.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B53, B57	P-24-101	P-24-102 (DWO)	P-24-103	P-24-104 (DWO)		Contained in A-24-101 and A-30-150 keying kits which are no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B54	P-16-161	P-16-162	P-16-163	P-16-164		A-16-106 current keying kit Also contained in the A-16-100 and A-16-101 keying kits which are no longer available for purchase.
B65	P-30-161	P-30-162	P-30-163	P-30-164		A-30-106 current keying kit Also contained in the A-30-150 keying kit which is no longer available for purchase.
B69	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	A-20-103 current keying kit containing only this series A-20-150 current keying kit containing this and the MZ13 series Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)
B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO) Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.
B85, B89, B97, B99 Locks made by Ortech sold by ASP	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B85, B89, B97, B99 Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B102, B107, B111 Locks made by Ortech sold by ASP	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
B110	P-24-121	P-24-122	P-24-123	P-24-124		A-24-103 current keying kit A-13-101 current keying kit for this series only
B114R (except ignition locks)	P-13-101 Or P-21-111	P-13-102 Or P-21-112	P-13-103 Or P-21-113	P-13-104 Or P-21-114		Also contained in the A-21-101 keying kit Also contained in the A-41-152 keying kit which is no longer available for purchase. Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.

Scroll down for more

CHEVROLET DOOR LOCKS

DA34	P-16-181	P-16-182	P-16-183	P-16-184		A-16-108 current keying kit Also contained in the A-16-101 keying kit which is no longer available for purchase.
DC1, DC3 (P1098V)	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
DWO4R DWO4C (DWO4CT6)	P-13-101 Or P-21-111	P-13-102 Or P-21-112	P-13-103 Or P-21-113	P-13-104 Or P-21-114		A-13-101 current keying kit for this series only Also contained in the A-21-101 keying kit Also contained in the A-41-152 keying kit which is no longer available for purchase. Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
HU100	P-23-121 (1R)	P-23-122 (2R)	P-23-123 (3R)	P-23-124 (4R)		A-23-103 current keying kit
	P-23-131 (1L)	P-23-132 (2L)	P-23-133 (3L)	P-23-134 (4L)		
TR33	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.
TR47 8-cut	#1 depth full size P-30-181	#2 depth full size P-30-182	#3 depth full size P-30-183	#4 depth full size P-30-184		A-30-108 current keying kit Also contained in the A-30-114 and A-30-150 keying kits which are no longer available for purchase.
	#1 depth split P-30-185	#2 depth split P-30-186	#3 depth split P-30-187	#4 depth split P-30-188		NOTE in this series #1 is the deepest cut, #4 is full width of the key blade
	#1 depth special design P-30-701	#2 depth special design P-30-702	#3 depth special design P-30-703	#4 depth special design P-30-704		These are special extra wide wafers which can replace the side-by-side split wafers. A-30-117 keying kit

Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (Previously RP6157 or RP6043)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using DWO4R, DWO4C keys - part no. P-31-100

For locks using HU100 2-track high security keys - part no. P-31-100

For locks using TR47, B110, DA34, DC1, TR33, and other similar keys (Japanese design locks)

P-00-100 - currently active part number - 100 springs per pack

This spring can also be substituted to use in locks using double bitted keys B97, etc.:

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
P-30-105	