

LINCOLN DOOR LOCKS

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. We supply coded or uncoded according to what is available to us from the manufacturer. All coded cylinders can be disassembled for rekeying, using the tumblers and keying kits listed. Coded locks may be substituted for locks listed as uncoded. Uncoded locks will never be substituted for locks listed as coded.
3. Identify which tumblers and keying kits to use according to the separate chart organized by the key blank numbers.
4. The dual part numbers for the same applications are the same part numbers at the same price. The number beginning with DL are Lockcraft part numbers. The ASP format part number (such as beginning with D-42-) are from the days when ASP sold only the original Ford production parts made by Hurd in Tennessee.
5. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
All	1952-58	H27	Coded lock RH without pawl	D-42-170	Coded lock LH without pawl	D-42-171	Coded pair: DP-42-170 The original pawls must be reused Use tumbler series P-42-181/185
All	1959-63	H27	No longer available – try classic Ford / Lincoln / Mercury parts specialists. Use tumbler series P-42-181/185 for locks with single sided keys, or P-42-131/135 for locks with double sided keys.				
All	1964-65	H27	Single coded lock with reversible pawl R&L	D-42-202	Coded pair Includes pawls R & L	DP-42-103	
			3-piece lock set Ignition + 2 doors Includes pawls R & L	S-42-001			
All	1966-80	H51	Uncoded lock round face	D-42-201	Coded pair round face	DL1550	Use tumbler series P-42-131/135
			Uncoded lock rectangular face non-lighted	D-42-175	Coded pair rectangular face non-lighted	DL1551	
Aviator	2003-05	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065				
Blackwood	2002-03	H75	Uncoded service pack	DL5885SP	Tumblers for assembly are included in the lock service pack. Pawls are not included, use P-42-322 for right side and P-42-323 for left side Face cap is available as P-42-267		
Continental	1981-84	H50	Uncoded lock non-lighted	D-42-176	Coded pair non-lighted	DL1591	Use tumbler series P-42-131/135
			Uncoded lock with lighted keyhole	D-42-174	Use tumbler series P-42-131/135		
Continental	1985-87	H54	Uncoded service pack non-lighted	D-42-205	Coded pair non-lighted	DP-42-106	Use face cap P-42-205 Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-203	Uncoded service pack LH, lighted keyhole	D-42-204	
Continental (10-cut locks)	1988-96	H54	Uncoded service pack RH, non-lighted	D-42-215	Uncoded service pack LH, non-lighted	D-42-216	Use face cap P-42-215 Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-229	Uncoded service pack LH, lighted keyhole	D-42-230	Use face cap P-42-216 Use tumbler series P-42-141/145
			Coded pair non-lighted Includes pawls R & L	DP-42-116			

Scroll down for more

LINCOLN DOOR LOCKS

Continental (8-cut locks)	1996-02	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065				
LS	2000-07	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065				
Mark LT	2006-11	H75	Uncoded service pack	DL5885SP	Tumblers for assembly are included in the lock service pack. Pawls are not included, use P-42-322 for right side and P-42-323 for left side Face cap is available as P-42-267		
Mark LT	2012-14	H75	Exact replacement lock available from Strattec. This lock is similar to DL5885SP which may work in an emergency.				
Mark VI	1981-84	H51	Uncoded lock non-lighted	D-42-176	Coded pair non-lighted	DL1591	Use tumbler series P-42-131/135
			Uncoded lock with lighted keyhole	D-42-174	Use tumbler series P-42-131/135		
Mark VII	1984-92	H54	Uncoded service pack non-lighted	D-42-205	Coded pair non-lighted	DP-42-106	Use face cap P-42-205 Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-203	Uncoded service pack LH, lighted keyhole	D-42-204	Use face cap P-42-203 Use tumbler series P-42-141/145
Mark VIII (10-cut locks)	1993-96	H54	Uncoded service pack RH, non-lighted	D-42-215	Uncoded service pack LH, non-lighted	D-42-216	Use face cap P-42-215 Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-229	Uncoded service pack LH, lighted keyhole	D-42-230	Use face cap P-42-216 Use tumbler series P-42-141/145
			Coded pair non-lighted Includes pawls R & L	DP-42-116			
Mark VIII (8-cut locks)	1996-98	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065				
MKS	2009-16	H75	Replacement locks available from Strattec				
MKX	2007-15	H75	Replacement locks available from Strattec				
MKZ	2006-16	H75	Replacement locks available from Strattec				
Navigator	1998-14	H75	Uncoded service pack	DL5885SP	Tumblers for assembly are included in the lock service pack. Pawls are not included, use P-42-322 for right side and P-42-323 for left side Face cap is available as P-42-267		
Navigator	2015-17	H75	Exact replacement lock available from Strattec. This lock is similar to DL5885SP which may work in an emergency.				
Navigator	2018-19	H75	Replacement locks available from Strattec				
Town Car	1981-84	H50	Uncoded lock non-lighted	D-42-176	Coded pair non-lighted	DL1591	Use tumbler series P-42-131/135
			Uncoded lock with lighted keyhole	D-42-174	Use tumbler series P-42-131/135		
Town Car	1985-89	H54	Uncoded service pack non-lighted	D-42-205	Coded pair non-lighted Includes pawls R & L	DP-42-106	Use face cap P-42-205 Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-203	Uncoded service pack LH, lighted keyhole	D-42-204	Use face cap P-42-203 Use tumbler series P-42-141/145
Town Car (10-cut locks)	1990-96	H54	Uncoded service pack RH, non-lighted	D-42-233	Uncoded service pack LH, non-lighted	D-42-234	Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-235	Uncoded service pack LH, lighted keyhole	D-42-236	Use tumbler series P-42-141/145
			Coded pair non-lighted	DP-42-134 (DWO)			
Town Car (8-cut locks)	1996-97	H75	Uncoded service pack RH, non-lighted Includes pawl	D-42-253	Uncoded service pack LH, non-lighted Includes pawl	D-42-254	see below for tumbler series
			Coded pair non-lighted Includes pawls R & L	DP-42-185 DL6182	Use tumbler series P-42-061/065		
Town Car	1998-03	H75	Uncoded service pack	DL5885SP	Tumblers for assembly are included in the lock service pack. Pawls are not included, use P-42-322 for right side and P-42-323 for left side Face cap is available as P-42-267		
Town Car (8-cut locks)	2004-11	H75	Uncoded service pack RH, non-lighted Includes pawl	D-42-253	Uncoded service pack LH, non-lighted Includes pawl	D-42-254	see below for tumbler series
			Coded pair non-lighted Includes pawls R & L	DP-42-185 DL6182	Use tumbler series P-42-061/065		
Versailles	1978-80	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135
Zephyr	2006-07	H75	Replacement locks available from Ford-Lincoln-Mercury dealers only.				

Scroll down for tumbler and keying kit information

LINCOLN DOOR LOCKS

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses. Some of these parts are no longer available for new purchase but are listed for the benefit of those who already have them (marked DWO / Discontinued When Out).

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Springs	Keying kits and Notes
H27 / H26	P-42-181	P-42-182	P-42-183	P-42-184	P-42-185	P-42-180	A-42-108 current keying kit – no longer available for purchase. Refill tumblers will continue to be available until sold out
H50 / H51	P-42-131	P-42-132	P-42-133	P-42-134	P-42-135	P-42-130	A-42-110 current keying kit Also contained in A-42-150 kit no longer available for purchase (DWO)
H54 (10-cut most models)	P-42-141	P-42-142	P-42-143	P-42-144	P-42-145	P-42-140	A-42-115 current keying kit Also contained in keying kits A-42-100, A-42-104, and A-42-150 keying kits no longer available for purchase (DWO)
H75 except below	P-42-061 RP5044	P-42-062 RP5045	P-42-063 RP5046	P-42-064 RP5047	P-42-065 RP5048	RP5043	A-42-109 keying kit (DWO) Refill packs continue to be available
H75 Zephyr	P-42-151	P-42-152	P-42-153	P-42-154	P-42-155	P-42-140	A-42-113 current keying kit
HU101	P-18-151 #1L	P-18-152 #2L	P-18-153 #3L	P-18-154 #4L	P-18-155 #5L	P-31-100	A-18-111 current keying kit
	P-18-161 #1R	P-18-162 #2R	P-18-163 #3R	P-18-164 #4R	P-18-165 #5R		