## **AUSTIN LOCKS**

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.

2. Identify which tumblers and keying kits to use according to the separate chart organized by the key blank numbers.

3. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

4. Remember – Driver side is LEFT, Passenger side is RIGHT

#### Ignition Locks

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
America, Healey, Mini, Morris Minor	pre 1970 non- locking steering	62FS	Coded plug (flat face) FS code series (62FS key blank)	C-14-301	Coded plug (turn knob face) – FS code series (62FS key blank)	C-14-302	Use tumbler series P-14-201/203 Keying kit A-14-230
		62FT	Coded plug (flat face) FT code series (62FT key blank)	B-14-210	Use tumbler series P-14-211/213 Keying kit A-14-230		
America, Healey, Mini, Morris Minor	pre 1970 some models	Various	Cylinder assembly C-00-101 Replacement for some locks using pin tumbler cylinders, some modification may be necessary to install this cylinder into the original lock housing. Exact replacements of this design are no longer available. Disassembly and rekeying of this lock is not recommended.				
Marina	All	X50	Replacement locks are not available, try general auto parts suppliers which specialize in classic British car parts				

#### Door Locks

Model	Years	Key	Part description	Part no.	Notes
America	All	62FS	Coded plug	C-14-301	Use tumbler series P-14-201/203
Healey 2000	All	62FT	Coded plug	D-14-235	Use tumbler series P-14-211/213
Marina	All	62FT	Coded plug	D-14-219	Use tumbler series P-14-211/213
Mini	All	62FS	Coded plug	D-14-240	Use tumbler series P-14-201/203
Morris Minor 2-door cars	All	62FS	Coded plug	D-14-243	Use tumbler series P-14-201/203
Morris Minor 2 door and 4-door cars	All	62FS	Coded plug	B-14-209	B-14-203 may be substituted, minor modification may be necessary Use tumbler series P-14-201/203
Morris Minor Traveler, Van	All	62FS	Coded plug	D-14-243	Use tumbler series P-14-201/203

#### Rear Compartment Locks

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes		
America	All	62FS	Complete lock	B-14-306	Coded plug	B-14-206	Use tumbler series P-14-201/203		
Healey 2000	All	62FS 62FT	Try classic British car parts suppliers Use tumbler series P-14-201/203 (FS and other code series using single sided keys) Use tumbler series p-14-211/214 (FT code series using double sided keys)						
Marina	All	62FT	Try classic British car parts suppliers. Use tumbler series P-14-211/213						
Mini, Mini Cooper	approx. 1972-00	62FS	Complete lock	B-14-307	Coded plug	B-14-209	Use tumbler series P-14-201/203		
Morris Minor 2-door and 4-door cars	all	62FS	Coded plug 2-door and 4-door cars						
Morris Minor Traveler, Van	All	62FS	Coded plug	B-14-202	Use tumbler series P-14-201/204				

Scroll down for more

# AUSTIN LOCKS

### **Glove Compartment Locks**

Model	Years	Key	Part description	Part no.	Notes
Marina	All	62FT	Complete lock	G-14-295	Disassembly and rekeying is not recommended

### Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses. Some of these parts are no longer available for new purchase but are listed for the benefit of those who already have them (marked DWO / Discontinued When Out).

Key Blank	#1 depth tumbler	#2 depth tumbler	#3 depth tumbler	Springs	Keying kits and Notes
62FS	P-14-201	P-14-202 (DWO)	P-14-203	P-14-20	Keying kits A-14-230 and A-14-111 which are no longer available for purchase. Refill packs will be available until current stock is sold out.
62FT	P-14-211 (DWO)	P-14-212	P-14-213	P-14-20	Keying kits A-14-230 and A-14-111 which are no longer available for purchase. Refill packs will be available until current stock is sold out.
X50					Tumblers and service parts are not available