See the separate section for Cadillac before 1967 model year.

General information as follows:

- 1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
- 2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
- 3. Unless specified otherwise pawls are not included with replacement locks, the original pawls must be reused.
- 4. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no. Part description Part no. Notes					
Allante	1986-93	B59	Replacement locks available from Cadillac / GM dealers only, other service parts not available from ASP.						
ATS	2013-18	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/135						
Calais	All		see Deville						
Cimarron	1982-88	GMA/K	Uncoded service pack	DL1580U	DL1580U Coded pair DL1580 Use face cap RP6036				
Catera	1997-02	B61	Uncoded plug D-23-311 Use tumbler series P-13-101/104 (P-21-111/114)						
Concours	1994-99		see Deville						
CT6	2016-18	HU100		Replacement locks available from Strattec Use tumbler series P-23-121/135					
CTS	2003-07	B97	Uncoded service pack	D-41-005	Use tumbler series P-41-121/124 for D-41-005 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new. Use face cap P-41-205				
СТЅ	2008-14	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.				
CTS	2014-18	HU100	Replacement locks available from Strattec Use tumbler series P-23-121/135						
Deville 2-door coupe & convertible	1967-68	GMA/K	Uncoded service pack	D-41-221	Coded pair DL1581 Use face cap RP6036 (P		Use face cap RP6036 (P-41-201)		
Deville 4-door	1967-68	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
Deville	1969-70	GMA/K	Uncoded service pack	D-41-221	Coded pair	DL1581	Use face cap RP6036 (P-41-201)		
	1971-93	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201)				
Deville			Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1973, 1977, 1981, and 1991-93 models only. Uncoded service package not available with other keyways as used 1971-72, 1974-76, 1978-80 and 1982-90. Use face cap RP6036 (P-41-201)				
			With lighted keyhole – re	eplacement loc	cks available from Strattec				

Scroll down for more

		1	I llandad sandas anali	D-41-243	I I la carda d'accordance de colo	D-41-244	T			
			Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	(DWO)				
Deville			Uncoded service pack	D-41-245	Uncoded service pack	D-41-246				
	1994-99	GMA/K	RH with alarm	(DWO)	LH with alarm	(DWO)				
		GWAR	Plugs are available as follows Uncoded plug for locks without alarm, unrestricted keyway accepts all GMA through GMK - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315							
Deville	2000-05	B97	Replacement locks available from Cadillac / GM dealers only. Use tumbler series P-41-111/114							
DTS	2006-11	B111	Replacement locks available from Cadillac / GM dealers only							
Eldorado	1967-70	GMA/K	Uncoded service pack	D-41-221	Coded pair	DL1581	Use face cap RP6036 (P-41-201)			
Eldorado	1971-81	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)			
			Uncoded service pack no alarm, non lighted	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)			
Eldorado	1982-85	GMA/K	Coded pair with factory alarm no lighted keyhole DP-41-115 Use face cap RP6036 (P-41-201)							
			With lighted keyhole – re	placement loc	cks available from Strattec					
Eldorado 1986-91			Uncoded service pack no alarm, non lighted, chrome	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)			
	1986-91	GMA/K	Coded pair with factory alarm no lighted keyhole chrome	DP-41-115	Use face cap RP6036 (P-41-201)					
			Uncoded service pack with factory alarm no lighted keyhole chrome	D-41-215	Use face cap RP6036 (P-41-201)					
			With lighted keyhole – replacement locks available from Strattec							
		GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)				
Eldorado			Uncoded service pack	D-41-245	Uncoded service pack	D-41-246				
	1992-00		RH with alarm	(DWO)	LH with alarm	(DWO)				
Lidorado	1002 00	OWN VIC	Plugs are available as follows Uncoded plug for locks without alarm - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-115							
ELR	2014-17	HU100	Replacement locks available from Strattec							
Escalade	1999-06	B99	Replacement locks avail	able from Stra	ttec					
Escalade	2007-14	B111	Replacement locks avail	Replacement locks available from Strattec						
Escalade	2015-18	HU100	Replacement locks available from Strattec							
Fleetwood	1969-70	GMA/K	Uncoded service pack	D-41-221	Coded pair	DL1581	Use face cap RP6036 (P-41-201			
		GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)			
Fleetwood			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201)					
	1971-96		Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1973, 1977, 1981, and 1991-93 models only. Uncoded service package not available with other keyways as used 1971-72, 1974-76, 1978-80 and 1982-90. Use face cap RP6036 (P-41-201)					
			,							
			With lighted keyhole – re	eplacement loc	L cks available from Strattec					
Seville	1974-81	GMA/K	With lighted keyhole – re Uncoded service pack	eplacement loc	cks available from Strattec Coded pair	DL1580	Use face cap RP6036 (P-41-201)			
Seville	1974-81	GMA/K		•		DL1580 DL1582	Use face cap RP6036 (P-41-201) Use face cap RP6036 (P-41-201)			
Seville Seville	1974-81 1982-85	GMA/K GMA/K	Uncoded service pack Uncoded service pack	DL1580U	Coded pair	DL1582	, , , , , ,			

Scroll down for more

Seville		GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)			
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201)					
	1986-91		Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1991-95 models only. Uncoded service package not available with other keyways as used 1986-90 Use face cap RP6036 (P-41-201)					
			With lighted keyhole – replacement locks available from Strattec							
Seville SLS, STS		GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)				
	1992-97		Uncoded service pack RH with alarm	D-41-245 (DWO)	Uncoded service pack LH with alarm	D-41-246 (DWO)				
	1992-91		Plugs are available as follows Uncoded plug for locks without alarm, unrestricted keyway accepts all GMA through GMK - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315							
Seville SLS, STS	1998-04	B99	Replacement locks available from Cadillac / GM dealers only. Parts to service original locks are available as follows: Face cap: P-41-203, Dust cover assembly: P-41-233 Use tumbler series P-41-111/114							
SRX	2004-09	B111	Uncoded service pack	Uncoded service pack D-41-003 Use tumbler series P-41-011/015 for D-41-003 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks so by GM dealers or originally installed on the car when it was new.						
SRX	2010-16	HU100	Uncoded service pack	D-23-245	Tumblers for assembly are not included with the service pack					
STS	2005-11	B111	Uncoded service pack	D-41-003	Use tumbler series P-41-011/0 003 tumblers may be used for lock by GM dealers or originally ins		old by ASP including some locks sold			
SUT	All		See Escalade							
XLR	2004-08		Remote access only, no lock cylinders							
XT5	2017-18	HU100			Replacement locks avail- Use tumbler series P-23-		attec			
XTS	2013-18	HU100			Replacement locks avail- Use tumbler series P-23-		attec			

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

The tumbler series used for each specific year and model application is listed in the notes section of the main lock application chart.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B61	P-13-101 Or P-21-111	P-13-102 Or P-21-112	P-13-103 Or P-21-113	P-13-104 Or P-21-114		A-13-101 current keying kit for this series only Also contained in the A-21-101 current keying kit Also contained in the A-41-152 keying kit which is no longer available for purchase. Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.

Scroll down for more

B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO) Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.
B85, B89, B97, B99 Locks made by Ortech sold by ASP	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B85. B89, B97, B99 Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B102, B107, B111 Locks made by Ortech sold by ASP	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
HU100	P-23-121 (1R) P-23-131 (1L)	P-23-122 (2R) P-23-132 (2L)	P-23-123 (3R) P-23-133 (3L)	P-23-124 (4R) P-23-134 (4L)		A-23-103 current keying kit

Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (Previously RP6157 or RP6043)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using B61 keys - part no. P-31-100

For locks using HU100 2-track high security keys - part no. P-31-100