

# CHEVROLET REAR COMPARTMENT LOCKS

**IMPORTANT:** See the separate Chevrolet Trucks section for all years Pickups, Vans, Avalanche, Blazer, Suburban, Tahoe, and other heavy duty trucks.

Also see the separate section for Chevrolet before 1967 model year.

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
3. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

| Model                  | Years      | Key   | Part description   | Part no. | Part description  | Part no. | Notes   |
|------------------------|------------|-------|--|----------|---|----------|---|
| Aveo                   | 2004-08    | DWO4R | Replacement locks available from Chevrolet / GM dealers only<br>Use tumbler series P-13-101/104 (P-21-111/114)   |          |   |          |   |
| Aveo hatchback         | 2009-11    | DWO4R | Complete lock  | B-50-119 | Use tumbler series P-13-101/104 (P-21-111/114)                              |          |   |
| Aveo sedan             | 2009-11    | DWO4R | Replacement locks available from Chevrolet / GM dealers only<br>Use tumbler series P-13-101/104 (P-21-111/114)   |          |   |          |   |
| Bel Air                | 1967-70    | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Bel Air                | 1971       | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Bel Air                | 1972-81    | GMA/K | Uncoded service pack Chrome  | TL1575U  | Coded lock black  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
|                        |            |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)                                    |
| Bel Air Station Wagon  | 1967-70    | GMA/K | Uncoded plug for manual tailgate   | B-41-302 | Switch locks for electric tailgate may be available by special request only |          |   |
| Bel Air Station Wagon  | 1971-76    | GMA/K | Replacement locks available from Strattec<br>Use tumbler series P-41-101/105   |          |   |          |   |
| Bel Air Station Wagon  | 1977-81    | GMA/K | Uncoded service pack   | DL1580U  | Coded lock (available as a pair only)                                       | DL1580   | Use face cap RP6036 (P-41-201)                                    |
| Biscayne               | 1967-70    | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Biscayne               | 1971       | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Biscayne               | 1972-81    | GMA/K | Uncoded service pack Chrome  | TL1575U  | Coded lock black  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
|                        |            |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)                                    |
| Biscayne Station Wagon | 1967-70    | GMA/K | Uncoded plug for manual tailgate   | B-41-302 | Switch locks for electric tailgate may be available by special request only |          |   |
| Biscayne Station Wagon | 1971-76    | GMA/K | Replacement locks available from Strattec<br>Use tumbler series P-41-101/105   |          |   |          |   |
| Biscayne Station Wagon | 1977-78    | GMA/K | Uncoded service pack   | DL1580U  | Coded lock (available as a pair only)                                       | DL1580   | Use face cap RP6036 (P-41-201)                                    |
| Beretta                | 1987-96    | GMA/K | Coded lock   | TL1530   |   |          |   |
| Camaro                 | 1967-12/69 | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1576   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                        |            |       | NOTE: The TL1576 / TL1576U lock with grooves for horizontal clip installation is officially the correct lock to use, as the lock installs on the car body, not the trunk lid. Some cars were manufactured using the vertical clip design lock, which is TL1575 / TL1575U. Try the TL1576 / TL1576U first, if it does not line up properly then use the vertical lock TL1575 / TL1575U. |          |   |          |   |

Scroll down for more

# CHEVROLET REAR COMPARTMENT LOCKS

|                                   |         |       |  |          |   |          |   |
|-----------------------------------|---------|-------|--|----------|---|----------|---|
| Camaro                            | 1/70-73 | GMA/K | Coded lock   | B-41-250 |   |          |   |
| Camaro                            | 1974-77 | GMA/K | Coded lock   | B-41-216 |   |          |   |
| Camaro                            | 1978-81 | GMA/K | Coded lock   | B-41-215 |   |          | Use face cap P-41-216   |
| Camaro                            | 1982-85 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                                   |         |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Camaro                            | 1986-92 | GMA/K | Uncoded service pack chrome  | B-41-217 | Uncoded service pack black  | B-41-218 | Face caps:<br>RP6036 (P-41-201) chrome<br>RP6520 (P-41-202) black |
| Camaro                            | 1993-02 | GMA/K | Coded lock   | TL1530   |   |          |   |
| Caprice                           | 1967-70 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Caprice                           | 1971    | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Caprice                           | 1972-96 | GMA/K | Uncoded service pack Chrome  | TL1575U  | Coded lock black  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
|                                   |         |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)                                    |
| Caprice Station Wagon             | 1967-70 | GMA/K | Uncoded plug for manual tailgate   | B-41-302 | Switch locks for electric tailgate may be available by special request only |          |   |
| Caprice Station Wagon             | 1971-76 | GMA/K | Replacement locks available from Strattec<br>Use tumbler series P-41-101/105   |          |   |          |   |
| Caprice Station Wagon             | 1977-91 | GMA/K | Uncoded service pack   | DL1580U  | Coded lock (available as a pair only)                                       | DL1580   | Use face cap RP6036 (P-41-201)                                    |
| Caprice Station Wagon             | 1992-96 | GMA/K | Replacement locks available from Strattec<br>Use tumbler series P-41-101/105   |          |   |          |   |
| Cavalier 2-door                   | 1982-94 | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1576   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                                   |         |       | Uncoded service pack black   | TL1524U  | Coded lock black  | TL1524   | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Cavalier 4-door and station wagon | 1982-94 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                                   |         |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Cavalier                          | 1995-05 | B86   | Replacement locks available from Strattec<br>Use tumbler series P-41-161/164   |          |   |          |   |
| Celebrity except station wagon    | 1983-91 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                                   |         |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Celebrity wagon                   | 1983-91 | GMA/K | Replacement locks available from Strattec  |          |   |          |   |
| Chevelle                          | 1967    | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1576   | Use face cap RP6036 (P-41-201)                                    |
| Chevelle                          | 1968-84 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)                                    |
| Chevelle wagon                    | 1967-72 | GMA/K | Uncoded plug for manual tailgate   | B-41-302 | Switch locks for electric tailgate may be available by special request only |          |   |
| Chevelle wagon                    | 1973-77 | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1576   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Chevette                          | 1975-79 | GMA/K | Uncoded plug   | B-41-301 |   |          |   |
| Chevette                          | 1980-87 | GMA/K | Uncoded plug   | B-41-301 |   |          |   |
| Chevy II                          | 1967-75 |       | see Nova 1967-75 (not the same as Nova 1984-88)  |          |   |          |   |
| Citation                          | 1978-84 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Cobalt                            | 2005-10 |       | Replacement locks available from Chevrolet / GM dealers only<br>Face cap must be removed to service original lock on the car, replacement caps not currently available |          |   |          |   |
| Corsica hatch.                    | 1987-96 | GMA/K | Replacement locks available from Strattec  |          |   |          |   |
| Corsica sedan                     | 1987-96 | GMA/K | Uncoded service pack chrome  | TL1575U  | Coded lock chrome   | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                                   |         |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Corvaire                          | 1967-69 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Equinox                           | 2005-18 |       | Remote release only, no lock cylinder  |          |   |          |   |
| Eurosport                         | 1983-91 |       | see Celebrity  |          |   |          |   |
| Impala                            | 1967-70 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Impala                            | 1971    | GMA/K | Uncoded service pack   | TL1576U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Impala                            | 1972-96 | GMA/K | Uncoded service pack   | TL1575U  | Coded lock  | TL1575   | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|                                   |         |       | Uncoded service pack black   | TL1523U  | Coded lock black  | TL1523   | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Impala                            | 2006-07 | B111  | Replacement locks available from Strattec  |          |   |          |   |
| Impala Station Wagon              | 1967-70 | GMA/K | Uncoded plug for manual tailgate   | B-41-302 | Switch locks for electric tailgate may be available by special request only |          |   |
| Impala Station Wagon              | 1971-76 | GMA/K | Replacement locks available from Strattec  |          |   |          |   |

Scroll down for more

# CHEVROLET REAR COMPARTMENT LOCKS

|   |         |       |  |                |   |        |   |
|---|---------|-------|--|----------------|---|--------|---|
| Impala Station Wagon                        | 1977-91 | GMA/K | Uncoded service pack   | DL1580U        | Coded lock (available as a pair only)   | DL1580 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Kingswood Station Wagon                     | 1967-70 | GMA/K | Uncoded plug for manual tailgate   | B-41-302       | Switch locks for electric tailgate may be available by special request only   |        |   |
| Kingswood Station Wagon                     | 1971-73 | GMA/K | Replacement locks available from Strattec                                    |                |   |        |   |
| Lumina                                      | 1989-94 | GMA/K | Uncoded service pack   | TL1575U        | Coded lock  | TL1575 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Lumina                                      | 1995-01 | GMA/K | Coded lock   | TL1530         |   |        |   |
| Lumina van                                  | 1990-96 | GMA/K | Replacement locks available from Strattec<br>Use tumbler series P-41-101/105 |                |   |        |   |
| Malibu except station wagon                 | 1967    | GMA/K | Uncoded service pack   | TL1576U        | Coded lock  | TL1576 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Malibu except station wagon                 | 1968-84 | GMA/K | Uncoded service pack   | TL1575U        | Coded lock  | TL1575 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Malibu wagon                                | 1967-72 | GMA/K | Uncoded plug for manual tailgate   | B-41-302       | Switch locks for electric tailgate may be available by special request only   |        |   |
| Malibu wagon                                | 1973-77 | GMA/K | Uncoded service pack   | TL1576U        | Coded lock  | TL1576 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Malibu wagon                                | 1978-83 | GMA/K | Coded lock   | TL1574         | NOTE: Some parts from the old lock may need to be reused. Also TL1574 is available in black trim only, chrome locks are no longer available.  |        |   |
| Malibu                                      | 1997-03 | B97   | Replacement locks available from Strattec<br>Use tumbler series P-41-161/164 |                |   |        |   |
| Malibu (except Malibu Classic)              | 2004-07 | B111  | Uncoded service pack   | B-41-006 (DWO) | Face cap must be removed to service original lock on the car, replacement caps included the B-41-006 service pack (not available separately)<br>Use tumbler series P-41-011/015   |        |   |
| Malibu Classic                              | 2004-05 | B97   | Replacement locks available from Strattec<br>Use tumbler series P-41-161/164 |                |   |        |   |
| Malibu Maxx                                 | 2004-07 |       | Remote release only, no lock cylinder  |                |   |        |   |
| Metro hatchback                             | 1995-97 | B65   | Coded lock (no pawl)   | D-33-207       | Previously sold as D-33-107<br>Reuse the original pawl or use P-33-303<br>Use face cap P-30-217<br>Use tumbler series P-30-161/164  |        |   |
| Metro sedan                                 | 1995-97 | B65   | Complete lock  | B-33-116       | Use face cap P-30-217<br>Use tumbler series P-30-161/164  |        |   |
| Metro                                       | 1998-01 | B69   | Uncoded service pack   | D-33-204       | The original pawl must be reused.<br>Use face cap P-20-265<br>Use tumbler series P-20-131/155   |        |   |
| Monte Carlo                                 | 1970-72 | GMA/K | Uncoded service pack   | TL1575U        | Coded lock  | TL1575 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Monte Carlo                                 | 1973    | GMA/K | Coded lock   | B-41-215       | Use face cap P-41-216   |        |   |
| Monte Carlo                                 | 1974-89 | GMA/K | Uncoded service pack chrome  | TL1575U        | Coded lock chrome   | TL1575 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
|   |         |       | Uncoded service pack black   | TL1523U        | Coded lock black  | TL1523 | Use face cap RP6520 (P-41-202)<br>Use tumbler series P-41-101/105 |
| Monte Carlo                                 | 1995-99 | GMA/K | Coded lock   | TL1530         |   |        |   |
| Monte Carlo                                 | 2000-05 | B97   | Replacement locks available from Strattec                                    |                |   |        |   |
| Monte Carlo                                 | 2006-08 | B111  | Replacement locks available from Chevrolet / GM dealers only.                |                |   |        |   |
| Monza Coupe                                 | 1975-81 | GMA/K | Uncoded service pack   | TL1576U        | Coded lock  | TL1576 | Use face cap RP6036 (P-41-201)                                    |
| Monza hatchback                             | 1975-78 | GMA/K | Coded lock   | B-41-215       | Use face cap P-41-216 (slanted design cap)  |        |   |
| Monza S coupe hatchback (variation of Vega) | 1978    | GMA/K | Uncoded service pack   | TL1576U        | Coded lock  | TL1576 | Use face cap RP6036 (P-41-201)                                    |
| Monza 2+2 Hatch Coupe (Standard trim)       | 1979-81 | GMA/K | Lock repair set  | B-41-279       | To use this set the original lock housing must be reused. This set contains uncoded plug, dust cover, and face cap so that the original lock can be rebuilt.<br>Face cap is available separately as part no. P-41-217 (stove top design cap, 0.75 inch thickness) |        |   |
| Monza sport hatch 2+2 deluxe trim           | 1979-81 | GMA/K | Uncoded plug   | B-41-215       | Use face cap P-41-216 (slanted design cap)  |        |   |
| Monza Station wagon                         | 1975-81 | GMA/K | Uncoded service pack   | DL1580U        | Coded lock (available as a pair only)   | DL1580 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Nomad Station Wagon                         | 1967-72 | GMA/K | Uncoded plug for manual tailgate   | B-41-302       | Switch locks for electric tailgate may be available by special request only   |        |   |
| Nova  | 1967-75 | GMA/K | Uncoded service pack   | TL1575U        | Coded lock  | TL1575 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |
| Nova hatchback                              | 1984-88 | TR33  | Coded lock (no turn knob)  | B-30-113       | The original pawl may need to be reused on some cars.<br>Use face cap P-30-214<br>Use tumbler series P-30-141/144   |        |   |
|   |         |       | Complete lock (with turn knob)   | B-30-167       | Use tumbler series P-30-141/144   |        |   |

Scroll down for more

# CHEVROLET REAR COMPARTMENT LOCKS

|                              |         |               |   |          |   |        |  |
|------------------------------|---------|---------------|---|----------|---|--------|--|
| Nova sedan                   | 1984-88 | TR33          | Complete lock<br>CL model<br>no turn knob   | B-30-131 | Use face cap P-30-271<br>Use tumbler series P-30-141/144                                      |        |  |
|                              |         |               | Complete lock<br>with turn knob   | B-30-140 | Use tumbler series P-30-141/144   |        |  |
| Prizm                        | 1998-02 | TR47<br>8-cut | Coded lock  | B-30-026 | The original pawl must be reused.<br>Use face cap P-30-217<br>Use tumbler series P-30-181/188 |        |  |
| Spectrum                     | 1985-91 | B53           | Complete lock   | B-24-105 | Use tumbler series P-24-101/104   |        |  |
| Sprint                       | 1985-86 | DC1           | Complete lock   | B-33-101 | Use tumbler series P-30-141/144   |        |  |
| Sprint                       | 1987-88 | DC1           | Complete lock   | B-33-102 | Use tumbler series P-30-141/144   |        |  |
| Sprint                       | 1989-94 |               | see GEO Metro 1989-94   |          |   |        |  |
| Townsmen<br>Station Wagon    | 1967-70 | GMA/K         | Uncoded plug for<br>manual tailgate   | B-41-302 | Switch locks for electric tailgate may be available by special request only                   |        |  |
| Townsmen<br>Station Wagon    | 1971-73 | GMA/K         | Replacement locks available from Strattec   |          |   |        |  |
| Tracker                      | 1999-04 | B69           | Uncoded service pack  | D-33-204 | The original pawl must be reused<br>Use face cap P-20-265<br>Use tumbler series P-20-131/155  |        |  |
| Uplander                     | 2005-07 | B107          | Locks using B107 keys, available from Chevrolet / GM dealers only.<br>Use tumbler series P-41-011/015 |          |   |        |  |
|                              |         | B86           | Locks using B86 keys, Replacement locks available from Strattec<br>Use tumbler series P-41-161/164    |          |   |        |  |
| Vega except<br>station wagon | 1971-77 | GMA/K         | Uncoded service pack  | TL1576U  | Coded lock  | TL1576 | Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105  |
| Vega station<br>wagon        | 1971-77 | GMA/K         | Uncoded service pack  | DL1580U  | Coded lock (available<br>as a pair only)  | DL1580 | Pawl is not included and is not<br>available from ASP<br>Use face cap RP6036 (P-41-201)<br>Use tumbler series P-41-101/105 |

## Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

To help avoid confusion, whenever possible the year and model section includes which tumbler series to use in the notes section.

| Key Blank             | Tumbler #1 depth             | Tumbler #2 depth             | Tumbler #3 depth             | Tumbler #4 depth             | Tumbler #5 depth             | Keying kits and Notes   |
|-----------------------|------------------------------|------------------------------|------------------------------|------------------------------|------------------------------|---|
| B10, B11              | P-41-101<br>RP6038<br>322051 | P-41-102<br>RP6039<br>322052 | P-41-103<br>RP6040<br>322053 | P-41-104<br>RP6041<br>322054 | P-41-105<br>RP6042<br>322055 | SK6035 keying kit   |
| B53, B57              | P-24-101                     | P-24-102<br>(DWO)            | P-24-103                     | P-24-104<br>(DWO)            |                              | Contained in A-24-101 and A-30-150 keying kits which are no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.          |
| B54                   | P-16-161                     | P-16-162                     | P-16-163                     | P-16-164                     |                              | A-16-106 current keying kit   |
| B65                   | P-30-161                     | P-30-162                     | P-30-163                     | P-30-164                     |                              | Also contained in the A-16-100 and A-16-101 keying kits which are no longer available for purchase.   |
| B69                   | P-20-131                     | P-20-132                     | P-20-133                     | P-20-144                     | P-20-155                     | A-30-106 current keying kit<br><br>A-20-103 current keying kit containing only this series<br><br>A-20-150 current keying kit containing this and the MZ13 series                         |
| B85, B89,<br>B97, B99 | P-41-161<br>RP6420           | P-41-162<br>RP6421           | P-41-163<br>RP6422           | P-41-164<br>RP6423           |                              | Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)<br>A-41-102 keying kit assembled by ASP (DWO)<br>SK6400 keying kit assembled by Lockcraft (DWO) |

# CHEVROLET REAR COMPARTMENT LOCKS

|   |                                     |                                     |                                     |                                     |                              |   |
|---|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|------------------------------|---|
| Locks made by Lockcraft and Strattec                | 322241                              | 322242                              | 322243                              | 322244                              |                              | Refill parts will be available until sold out, tumblers made by Strattec will also work in these locks.   |
| B85, B89, B97, B99 Locks made by Ortech sold by ASP | P-41-121                            | P-41-122                            | P-41-123                            | P-41-124                            |                              | A-41-104 current keying kit<br>Also contained in keying kit A-41-150 which is no longer available for purchase  |
| B85, B89, B97, B99 Locks made by HUF                | P-41-111                            | P-41-112                            | P-41-113                            | P-41-114                            |                              | A-41-103 current keying kit<br>Also contained in keying kit A-41-150 which is no longer available for purchase  |
| B102, B107, B111 Locks made by Ortech sold by ASP   | P-41-011                            | P-41-012                            | P-41-013                            | P-41-014                            | P-41-015                     | Contained in keying kit A-41-152 which is no longer available for purchase.<br>Refill packs of the individual tumblers will continue to be available until sold out.  |
| B102, B107, B111 Locks made by Strattec             |                                     |                                     |                                     |                                     |                              | These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.   |
| B110  | P-24-121                            | P-24-122                            | P-24-123                            | P-24-124                            |                              | A-24-103 current keying kit   |
| DA34  | P-16-181                            | P-16-182                            | P-16-183                            | P-16-184                            |                              | A-16-108 current keying kit<br>Also contained in the A-16-101 keying kit which is no longer available for purchase.   |
| DC1, DC3 (P1098V)                                   | P-30-141                            | P-30-142                            | P-30-143                            | P-30-144                            |                              | A-30-116 current keying kit<br>Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.  |
| DWO4R<br>DWO4C<br>(DWO4CT6)                         | P-13-101<br>Or<br>P-21-111          | P-13-102<br>Or<br>P-21-112          | P-13-103<br>Or<br>P-21-113          | P-13-104<br>Or<br>P-21-114          |                              | A-13-101 current keying kit for this series only<br>Also contained in the A-21-101 keying kit<br>Also contained in the A-41-152 keying kit which is no longer available for purchase.<br>Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price. |
| GMA through GMK (single sided keys, sidebar locks)  | P-41-101<br>RP6038<br>322051        | P-41-102<br>RP6039<br>322052        | P-41-103<br>RP6040<br>322053        | P-41-104<br>RP6041<br>322054        | P-41-105<br>RP6042<br>322055 | SK6035 keying kit supplied by ASP   |
| HU100   | P-23-121<br>(1R)                    | P-23-122<br>(2R)                    | P-23-123<br>(3R)                    | P-23-124<br>(4R)                    |                              | A-23-103 current keying kit   |
|   | P-23-131<br>(1L)                    | P-23-132<br>(2L)                    | P-23-133<br>(3L)                    | P-23-134<br>(4L)                    |                              |   |
| TR33  | P-30-141                            | P-30-142                            | P-30-143                            | P-30-144                            |                              | A-30-116 current keying kit<br>Also contained in the A-30-104 and A-30-150 keying kits which are no longer available for purchase.  |
| TR47 8-cut  | #1 depth full size<br>P-30-181      | #2 depth full size<br>P-30-182      | #3 depth full size<br>P-30-183      | #4 depth full size<br>P-30-184      |                              | A-30-108 current keying kit<br>Also contained in the A-30-114 and A-30-150 keying kits which are no longer available for purchase.  |
|   | #1 depth split<br>P-30-185          | #2 depth split<br>P-30-186          | #3 depth split<br>P-30-187          | #4 depth split<br>P-30-188          |                              | NOTE in this series #1 is the deepest cut, #4 is full width of the key blade  |
|   | #1 depth special design<br>P-30-701 | #2 depth special design<br>P-30-702 | #3 depth special design<br>P-30-703 | #4 depth special design<br>P-30-704 |                              | These are special extra wide wafers which can replace the side-by-side split wafers.<br>A-30-117 keying kit   |

## Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (Previously RP6157 or RP6043)

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using DWO4R, DWO4C keys - part no. P-31-100

For locks using HU100 2-track high security keys - part no. P-31-100

Scroll down for more

# CHEVROLET REAR COMPARTMENT LOCKS

For locks using TR47, B110, DA34, DC1, TR33, and other similar keys (Japanese design locks), can also be substituted to use in locks using double bitted keys B97, etc.: P-00-100 - currently active part number - 100 springs per pack

Part numbers previously used, now superseded to P-00-100

|          |          |
|----------|----------|
| P-16-105 | P-30-108 |
| P-19-100 | RP6546   |
| P-20-105 | RP6612   |
| P-20-115 | RP6731   |
| P-24-105 | RP6822   |
| P-30-105 |          |