DAEWOO LOCKS

General information as follows:

- 1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
- 2. Remember, left side (LH) is DRIVER side, right side (RH) is PASSENGER side

IGNITION LOCKS

Model	Years	Key	Part description	Part no.	Notes
Lanos	1999-02	DWO5RAP	Coded cylinder	C-50-110	NOTE: C-50-110 replaces C-50-101
Leganza	1999-02	DWO5AP	Coded cylinder	C-50-103	
Nubira	1999-02	DWO4RAP	Coded cylinder	C-50-110	NOTE: C-50-110 replaces C-50-102

DOOR LOCKS

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Lanos	1999-02	DWO5RAP	Complete lock RH	D-50-101	Complete lock LH	D-50-102	
Leganza	1999-02	DWO5AP	Complete lock RH	D-50-105	Complete lock LH	D-50-106	
Nubira	1999-02	DWO4RAP	Complete lock RH	D-50-103	Complete lock LH	D-50-104	

REAR COMPARTMENT LOCKS

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
Lanos	1998-02	DWO5RAP	Complete lock	B-50-101			
Leganza	1998-02	DWO5AP	Complete lock without factory alarm switch	B-50-106	Complete lock with factory alarm switch	B-50-113	
Nubira hatchback	1998-00	DWO4RAP	Complete lock without factory alarm switch	B-50-109	Complete lock with factory alarm switch	B-50-118	
Nubira sedan	1998-99	DWO4RAP	Complete lock without factory alarm switch	B-50-102	Complete lock with factory alarm switch	B-50-111	
Nubira sedan	2000-02	DWO4RAP	Replacement locks are not available from ASP Use face cap P-40-201				
Nubira station wagon	1998-02	DWO4RAP	Complete lock without factory alarm switch	B-50-110	Complete lock with factory alarm switch	B-50-112	

GLOVE COMPARTMENT LOCKS

Model	Years	Key	Part description	Part no.	Notes
Logonzo	ganza 1998-02 DWO5AP	Complete lock brown	G-50-106	Disassembly and rekeying is not recommended	
Leganza 1998-02	DWOSAP	Complete lock gray	G-50-105	Disassembly and rekeying is not recommended	
Nubira	1998-02	DWO4RAP	Complete lock brown	G-50-104	Disassembly and rekeying is not recommended

TUMBLERS AND KEYING KITS

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Springs	Keying kits and Notes
All	P-21-111 Or P-13-101	P-21-112 Or P-13-102	P-21-113 Or P-13-103	P-21-114 Or P-13-104	P-31-100	A-13-101 current keying kit containing only this series Also included in the A-21-101 keying kit for Mercedes which also contains other series Also contained in the A-41-152 keying kit which is no longer available for purchase. Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.