

FORD IGNITION LOCKS

IMPORTANT: See the separate Ford Trucks section for Pickups, Vans, and heavy duty trucks. Sport Utility Vehicles such as Bronco, Escape, Explorer, Expedition, and Excursion are in this section.

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. The dual part numbers for the same applications are the same part numbers at the same price. The number beginning with LC are Lockcraft part numbers. The ASP format part number (such as beginning with C-42-) are from the days when ASP sold only the original Ford production parts made by Hurd in Tennessee. The 10-cut Ford ignition locks now sold by ASP are those which are approved by Ford Motor Co. the same as previously produced by Hurd.
3. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

Model	Years	Key	Part description	Part no.	Part description	Part no.,	Notes
300	1963	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-131/135
Aerostar	1986-92	H54	Coded cylinder	C-42-110	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Aerostar	1993-11/95	H54	Coded cylinder	C-42-150	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Aerostar	11/95-97	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				
Aspire	1994-99	H70	Coded cylinder	C-40-103	Use tumbler series P-40-101/104		
Bronco	1966-77	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-181/185
Bronco	1978-79	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Bronco	1980-86	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Bronco	1987-91	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Bronco	1992-2/95	H54	Coded cylinder	C-42-150	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Bronco	3/95-97	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				
Bronco II	1984	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Bronco II	1985-90	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Bronco Sport	2020-25	HU198	Replacement locks and parts available from Strattec				
C-Max	2013-18	HU101	Uncoded cylinder	C-18-309	Use tumbler series P-18-151/165		
Contour	1995-00	H54	Uncoded cylinder	C-42-167			These locks are now in short supply due to closing of the Hurd factory
			NOTE TO AVOID CONFUSION: Original Valeo keys have an extra groove down the blade so it looks like an 8-cut, but otherwise it is 10-cut and all 10-cut keys without the groove can be used.				
Cortina	1965-70	62FT	Uncoded plug (except with locking steering)	B-14-210	Use tumbler series P-14-211/213		
Cortina	1971-76	X86	Coded cylinder	C-18-102	Use tumbler series P-18-111/114		

Scroll down for more

FORD IGNITION LOCKS

Country Sedan Country Squire station wagons	1952-59	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Country Sedan Country Squire station wagons	1960-64	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-131/135
Country Sedan Country Squire station wagons	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Country Sedan Country Squire station wagons	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Country Sedan Country Squire station wagons	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Country Sedan Country Squire station wagons	2/76-78	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Country Sedan Country Squire station wagons	1979-89	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Country Sedan Country Squire station wagons	1990-91	H54	Coded cylinder	C-42-150	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Crestline	1952-54	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Crown Victoria	1983-89	H54	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Crown Victoria	1990-95	H54	Coded cylinder	C-42-150	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Crown Victoria	1996- 3/05	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				
Crown Victoria	4/05-08	H75	Use tumbler series P-42-151/155 Replacement lock service package now available from Strattec				
Custom and Customline	1952-59	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Custom and Customline	1960-64	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-131/135
Custom	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Custom	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Custom	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Custom	2/76-78	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Custom	1979-82	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Del Rio Station wagon	1957	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ecosport	2018-22	HU101	Replacement locks are available from Ford dealers only				
Edge	2007-14	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Edge	2015-17	HU101	Uncoded service pack	C-18-309	Use tumbler series P-18-151/165		
Escape	2001-07	H75	Uncoded cylinder (no turn knob)	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
			Uncoded service pack (with turn knob)	C-42-171 (DWO)	Replacement locks are now available only from Mazda or Ford dealers only		

Scroll down for more

FORD IGNITION LOCKS

Escape	2008-12	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack			
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.					
Escape	2013-19	HU101	Uncoded service pack	C-18-309	Use tumbler series P-18-151/165			
Escape	2020-25	HU198	Replacement locks and parts available from Strattec					
Escort	1981-87	H51	Coded cylinder chrome	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key			
			Coded cylinder black	C-42-409 LC1409	Uncoded cylinder	LC1409U	Use tumbler series P-42-131/135	
Escort	1988-90	H54	Coded cylinder (Chrome only)	C-42-110	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key. Also locks with black knob are no longer available.			
Escort	1991-93	H54	Uncoded cylinder manual transmission	C-42-193	Complete lock & switch manual trans	C-42-291	Use tumbler series P-42-191/195	
			Uncoded cylinder automatic transmission	C-42-194	Complete lock & switch automatic trans.	C-42-292	Use tumbler series P-42-191/195	
Escort	1994-11/30/95	H54	Uncoded cylinder manual transmission	C-42-193	Complete lock & switch manual trans	C-42-293	Use tumbler series P-42-191/195	
			Uncoded cylinder automatic transmission	C-42-194	Complete lock & switch automatic trans.	C-42-294	Use tumbler series P-42-191/195	
Escort	12/1/95 to 1996	MZ19	Complete lock & switch automatic transmission	C-20-244 (DWO)	Complete lock & switch manual trans	C-20-245 (DWO)	Use tumbler series P-20-131/155	
Escort	1997-02	X221	Complete lock & switch automatic transmission	C-20-228 (DWO)	Complete lock & switch manual trans	C-20-227 (DWO)	Use tumbler series P-20-131/155	
Excursion	2000-05	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055	
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.					
EXP	1981-87	H51	Coded cylinder chrome	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key			
			Coded cylinder black	C-42-409 LC1409	Uncoded cylinder	LC1409U	Use tumbler series P-42-131/135	
Expedition	1997-02	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055	
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.					
Expedition	2003-19	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack			
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.					
Explorer	1991-94	H54	Coded cylinder	C-42-110	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key			
Explorer	1995	H54	Coded cylinder	C-42-150	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key			
Explorer	1996-00	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055	
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.					
Explorer 2-door	2001-05	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055	
NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.								
Explorer 4-door	2001-15 + some 2016-18	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack			
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.					
Explorer 4-door	some 2016-19	HU101	Uncoded service pack	C-18-309	Use tumbler series P-18-151/165			
Explorer Sport Trac (Pickup body)	2001-07	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055	
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.					

Scroll down for more

FORD IGNITION LOCKS

Explorer Sport Trac (Pickup body)	2008-10	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Fairlane	1955-59	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Fairlane	1960-65	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-181/185
Fairlane	1966-70	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Fairmont	1978-83	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Falcon	1960-65	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-181/185
Falcon	1966-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Falcon	1970	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Festiva	1988-89	MZ13	Uncoded plug	C-20-311	Complete lock & switch	C-20-213	Use tumbler series P-20-111/164
Festiva	1990-93	MZ13	Uncoded plug	C-20-311	Use tumbler series P-20-111/164		
			Complete lock & switch automatic transmission	C-20-217	Complete lock & switch manual transmission	C-20-218	Use tumbler series P-20-111/164
Fiesta	1978-81	X86	Coded cylinder	C-18-103	Use tumbler series P-18-111/114		
Fiesta	2011-19	HU101	Coded cylinder	C-18-108	Use tumbler series P-18-151/165		
Five Hundred	2005-07	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Flex	2009-19	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Focus	2000-11	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Focus	2012-19	HU101	Uncoded service pack	C-18-309	Use tumbler series P-18-151/165		
Freestar	2004-08	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				
Freestyle	2005-07	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				

Scroll down for more

FORD IGNITION LOCKS

Fusion	2006-12	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Fusion	2013-20	HU101	Uncoded service pack	C-18-309	Use tumbler series P-18-151/165		
Galaxie	1959	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Galaxie	1960-64	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-131/135
Galaxie	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Galaxie	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Galaxie	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Galaxie	2/76-78	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Granada	1974 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Granada	2/76-80	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Granada	1981-82	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD	2/76-78	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD	1979-82	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD	1983-86	H51	Coded cylinder	C-42-409 LC1409	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
LTD II	1977-79	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mainline	1952-56	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Maverick	early 1970	H51	Coded cylinder non locking steering	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Maverick	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Maverick	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Maverick	2/76-78	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mustang	1964-66	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-181/185
Mustang	1967-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mustang	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mustang	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mustang II	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mustang II	2/76-78	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Mustang	1979-93	H51	Coded cylinder chrome	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
			Coded cylinder black	C-42-409 LC1409	Uncoded cylinder	LC1409U	Use tumbler series P-42-131/135
Mustang	1994-95	H54	Coded cylinder Cars without transponder	C-42-140	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
			Coded cylinder cars with transponder (larger face to accept transponder key)	C-42-149	Use tumbler series P-42-191/195		
Mustang	1996-04	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				

Scroll down for more

FORD IGNITION LOCKS

Mustang	2005-14	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack	Uncoded cylinder	C-42-197 see note
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Mustang	2015-25	HU101	Replacement locks available from Ford dealers only (pushbutton start)				
Parklane station wagon	1956	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Pinto	1971 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Pinto	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Pinto	2/76-80	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Police Interceptor Util.	2019	HU101	Uncoded service pack	C-18-309	Use tumbler series P-18-151/165		
Probe	1989-92	MZ13	Uncoded plug	C-20-311	Use tumbler series P-20-111/164		
			Complete lock & switch automatic transmission	C-20-215	Complete lock & switch manual transmission	C-20-216	Use tumbler series P-20-111/164
Probe	1993-97	MZ19	Complete lock & switch manual trans	C-20-219	Coded cylinder (SEE NOTE)	C-20-109 (DWO)	Use tumbler series P-20-131/155
			Complete lock & switch automatic trans	C-20-220	Uncoded cylinder	C-20-110	Use tumbler series P-20-131/155
			NOTE: C-20-109 cylinder is discontinued when out, now must use complete lock assembly C-20-219.				
Ranch Wagon	1952-59	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranch Wagon	1960-64	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-131/135
Ranch Wagon	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranch Wagon	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranch Wagon	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranchero	1957-59	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranchero	1960-64	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-131/135
Ranchero	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranchero	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranchero	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Ranchero	2/76-79	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Taurus	1986-89	H54	Uncoded cylinder	C-42-137	Coded cylinder	C-42-130	Use tumbler series P-42-191/195
Taurus	1990-95	H54	Coded cylinder	C-42-140	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Taurus	1996-07	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				
Taurus	2008-19	H75	Uncoded cylinder	C-42-197 see note	Tumblers included in the uncoded service pack		
			NOTE: C-42-197 replaces C-42-187. C-42-197 does not include the large black clip which fits onto the rear of the plug as used on some models. The retaining pin of C-42-197 cannot be depressed to remove the cylinder assembly from the steering column lock housing until the plug is turned. This is different from the C-42-187 design lock that the clip interlocks with the housing to prevent removing the cylinder without turning the cylinder. The clip from the lock being replaced may be installed on the back of the new C-42-197 lock, although because of the different retaining pin design the interlocking function of the clip is not important for security against unauthorized removal of the cylinder assembly from the lock housing.				
Tempo	1984-87	H51	Coded cylinder chrome	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
			Coded cylinder black	C-42-409 LC1409	Uncoded cylinder	LC1409U	Use tumbler series P-42-131/135
Tempo	1988-94	H54	Coded cylinder (Chrome only)	C-42-110	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key. Also locks with black knob are no longer available.		
Thunderbird	1955-59	H27	Coded cylinder	C-42-400 LC1400	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	1960-64	H27	Coded cylinder	C-42-401 LC1401	Uncoded cylinder	LC1401U	Use tumbler series P-42-181/185

Scroll down for more

FORD IGNITION LOCKS

Thunderbird	1965-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	2/76-79	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	1980-82	H51	Coded cylinder	C-42-407 LC1407	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	1983-84	H51	Coded cylinder	C-42-409 LC1409	Uncoded cylinder	LC1409U	Use tumbler series P-42-131/135
Thunderbird	1984-93	H54	Coded cylinder (Chrome only)	C-42-110	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key. Also locks with black knob are no longer available.		
Thunderbird	1994-96	H54	Coded cylinder	C-42-140	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Thunderbird	1996-99	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				
Thunderbird	2001-05	H75	Replacement locks available from Strattec Use tumbler series P-42-051/055				
Torino	1968-69	H51	Coded cylinder	C-42-402 LC1402	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Torino	1970 to 5/14/73	H51	Coded cylinder	C-42-404 LC1404	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Torino	5/15/73 to 1/76	H51	Coded cylinder	C-42-405 LC1405	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Torino	2/76-end of model	H51	Coded cylinder	C-42-406 LC1406	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Windstar	1995-96	H54	Coded cylinder	C-42-140	Uncoded cylinder is no longer available. Coded cylinders can be easily disassembled and rekeyed to the original car key		
Windstar	1996-03	H75	Uncoded cylinder	C-42-195 see note	Coded cylinder	C-42-184 LC6177	Use tumbler series P-42-051/055
			NOTE: C-42-195 replaces C-42-182, C-42-185, and LC6177U. C-42-195 is the no-sidebar design lock and includes tumblers and springs for assembly.				

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses. Some of these parts are no longer available for new purchase but are listed for the benefit of those who already have them (marked DWO / Discontinued When Out).

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Springs	Keying kits and Notes
62FT	P-14-211 (DWO)	P-14-212	P-14-213			P-14-200	Contained in A-14-230 and A-14-111 keying kits no longer available for purchase (DWO) Refill packs of the individual tumblers will continue to be available until sold out
FO21 (Tibbe)	P-18-131	P-18-132	P-18-133	P-18-134		Springs not used in Tibbe locks	A-18-110 current keying kit Also contained in A-18-108 and A-18-109 keying kits no longer available for purchase (DWO)
H27 / H26	P-42-181	P-42-182	P-42-183	P-42-184	P-42-185	P-42-180	A-42-108 current keying kit – no longer available for purchase. Refill tumblers will continue to be available until sold out
H50 / H51 pin tumblers	P-42-131	P-42-132	P-42-133	P-42-134	P-42-135	P-42-130	A-42-110 current keying kit Also contained in A-42-150 kit no longer available for purchase (DWO)
H54	P-42-191 (DWO)	P-42-192	P-42-193	P-42-194	P-42-195	P-42-190	A-42-111 current keying kit no longer available for purchase. Refill tumblers will continue to be available until sold out Also contained in A-42-150 keying kits no longer available for purchase (DWO)
H70	P-40-101	P-40-102	P-40-103	P-40-104		P-00-100	A-40-101 current keying kit
H75 sidebar locks only	P-42-051 RP5049	P-42-052 RP5050	P-42-053 RP5052	P-42-054 RP5053	P-42-055 RP5054	RP5055	A-42-109 keying kit (DWO) Refill packs will be available until sold out. Refill packs are also available from Strattec
H75 locks without sidebar	P-42-151	P-42-152	P-42-153	P-42-154	P-42-155	P-42-140	A-42-113 current keying kit (Used on Crown Victoria, Focus, Escape, and others)

Scroll down for more

FORD IGNITION LOCKS

HU101	P-18-151 #1L	P-18-152 #2L	P-18-153 #3L	P-18-154 #4L	P-18-155 #5L	P-31-100	A-18-111 current keying kit
	P-18-161 #1R	P-18-162 #2R	P-18-163 #3R	P-18-164 #4R	P-18-165 #5R		
MZ13	P-20-111	P-20-162	P-20-163	P-20-164		P-00-100	A-20-150 current keying kit containing this and the MZ19 series Also contained in keying kit A-20-100 and A-20-101 no longer available for purchase (DWO)
MZ19	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	P-00-100	A-20-103 current keying kit containing only this series A-20-150 current keying kit containing this and the MZ13 series Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)
RV4	P-14-121	P-14-122	P-14-123 (DWO)	P-14-124	P-14-125 (#2 depth alternate design)	P-31-100	Contained in A-14-101, A-14-106, and A-14-113 keying kits no longer available for purchase (DWO) Refill packs of the individual tumblers will continue to be available until sold out
X26	P-20-111	P-20-112	P-20-113			P-00-100	Contained in keying kits A-20-101 and A-20-100 no longer available for purchase (DWO). Refill packs of the individual tumblers will continue to be available until sold out
X36							Tumblers and service parts are not available
X86 (TC code series)	P-18-111	P-18-112	P-18-113	P-18-114		P-31-100	A-18-107 current keying kit
X221	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	P-00-100	A-20-103 current keying kit containing only this series A-20-150 current keying kit containing this and the MZ13 series Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)