

MERCURY DOOR LOCKS

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. We supply coded or uncoded according to what is available to us from the manufacturer. All coded cylinders can be disassembled for rekeying, using the tumblers and keying kits listed. Coded locks may be substituted for locks listed as uncoded. Uncoded locks will never be substituted for locks listed as coded.
3. Identify which tumblers and keying kits to use according to the separate chart organized by the key blank numbers.
4. The dual part numbers for the same applications are the same part numbers at the same price. The number beginning with DL are Lockcraft part numbers. The ASP format part number (such as beginning with D-42-) are from the days when ASP sold only the original Ford production parts made by Hurd in Tennessee.
5. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
All	1952-58	H27	Coded lock RH without pawl	D-42-170	Coded lock LH without pawl	D-42-171	Coded pair: DP-42-170 The original pawls must be reused Use tumbler series P-42-181/185
All	1959-60	H27	No longer available – try classic Ford / Mercury parts specialists. Use tumbler series P-42-181/185				
All except Comet	1961-64	H27	Single lock with reversible pawl R&L	D-42-202	Use tumbler series P-42-181/185		
			Coded pair Includes pawls R & L	DP-42-103	3-piece set Ignition + 2 doors Includes pawls R & L	S-42-001	
Bobcat	1971-80	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135
Caliente	1966-78	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135
Capri	1970-75	X21, X22	No longer available – try classic Ford / Mercury parts specialists. Tumblers and service parts not available.				
Capri	1976-78	X86	Uncoded plug	D-18-105 (DWO)	Use tumbler series P-18-111/114		
Capri	1979-80	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135
Capri	1981-86	H50	Uncoded lock chrome	D-42-231	Coded pair chrome	DL1590	Use tumbler series P-42-131/135
			Uncoded lock black	D-42-232	Coded pair black	DP-42-148	Use tumbler series P-42-131/135
			Uncoded lock black cap chrome dust cover	D-42-242	Coded pair black cap chrome dust cover	DP-42-104	Use tumbler series P-42-131/135
Capri	1990-94	MZ13	Coded lock with reversible pawl R&L	D-20-101	Coded pair	DP-20-101	Use face cap P-20-211 Use tumbler series P-20-111/164
Colony Park station wagon	All		see Monterey, Marquis, Grand Marquis				
Comet	1960-63	H27	Coded lock RH without pawl	D-42-170	Coded lock LH without pawl	D-42-171	Coded pair: DP-42-170 The original pawls must be reused Use tumbler series P-42-181/185
Comet	1964-65	H27	Single lock with reversible pawl R&L	D-42-202	Use tumbler series P-42-181/185		
			Coded pair Includes pawls R & L	DP-42-103	3-piece set Ignition + 2 doors Includes pawls R & L	S-42-001	
Comet	1966-78	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135

Scroll down for more

MERCURY DOOR LOCKS

Cougar	1967-79	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135		
Cougar 2-door and XR7	1980	H51	Uncoded lock	D-42-175	Coded pair	DL1551	Use tumbler series P-42-131/135		
Cougar 2-door and XR7	1981-82	H50	Uncoded lock non-lighted	D-42-176	Coded pair	DL1591	Use tumbler series P-42-131/135		
			Uncoded lock lighted keyhole	D-42-174	Use tumbler series P-42-131/135				
Cougar 4-door sedan & wagon	1981-82	H50	Uncoded lock non-lighted	D-42-231	Coded pair	DL1590	Use tumbler series P-42-131/135		
			Uncoded lock lighted keyhole	D-42-174	Use tumbler series P-42-131/135				
Cougar (pin tumbler locks)	1983-84	H50	Uncoded lock chrome non-lighted	D-42-231	Coded pair – chrome	DL1590	Use tumbler series P-42-131/135		
			Uncoded lock black non-lighted	D-42-232	Coded pair - black	DP-42-148	Use tumbler series P-42-131/135		
			Uncoded lock with lighted keyhole (chrome only)	D-42-174	Use tumbler series P-42-131/135				
Cougar (10-cut locks)	1984-1/2 to 1988	H54	Uncoded service pack non-lighted, chrome	D-42-221	Coded pair – chrome	DP-42-122	Use face cap P-42-201 Use tumbler series P-42-141/145		
			Uncoded service pack non-lighted, black	D-42-222	Use face cap P-42-202 Use tumbler series P-42-141/145				
			Uncoded service pack RH, lighted keyhole chrome	D-42-203	Uncoded service pack LH, lighted keyhole chrome	D-42-204	Use face cap P-42-203 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole black	D-42-206	Uncoded service pack LH, lighted keyhole black	D-42-207	Use face cap P-42-204 Use tumbler series P-42-141/145		
Cougar (10-cut locks)	1989-95	H54	Uncoded service pack RH, non-lighted	D-42-217	Uncoded service pack LH, non-lighted	D-42-218	Use face cap right side P-42-217 Use face cap left side P-42-218 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole	D-42-219	Uncoded service pack LH, lighted keyhole	D-42-220	Use face cap right side P-42-219 Use face cap left side P-42-220 Use tumbler series P-42-141/145		
			Coded pair non-lighted Includes pawls R & L	DP-42-118					
Cougar (10-cut locks)	early 1996	H54	Uncoded service pack RH, non-lighted	D-42-243	Uncoded service pack LH, non-lighted	D-42-244	Use face cap right side P-42-270 Use face cap left side P-42-271 Use tumbler series P-42-141/145		
Cougar (8-cut locks)	1996-97	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065						
Cougar	1999-02	H54	Uncoded service pack RH	D-42-249	Uncoded service pack LH	D-42-250	Use face cap P-42-278 Use tumbler series P-42-141/145		
			NOTE TO AVOID CONFUSION: Original Valeo keys have an extra groove down the blade so it looks like an 8-cut, but otherwise it is 10-cut and all 10-cut keys without the groove can be used.						
Grand Marquis	1983-89	H50	Uncoded lock non-lighted	D-42-231	Coded pair	DL1590	Use tumbler series P-42-131/135		
			Uncoded lock with lighted keyhole	D-42-174	Use tumbler series P-42-131/135				
Grand Marquis	1990-91	H54	Uncoded service pack non-lighted	D-42-221	Coded pair – chrome non-lighted Includes pawls R & L	DP-42-122	Use face cap P-42-201 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole	D-42-203	Uncoded service pack LH, lighted keyhole	D-42-204	Use face cap P-42-203 Use tumbler series P-42-141/145		
Grand Marquis (10-cut locks)	1992-95	H54	Uncoded service pack RH, non-lighted	D-42-233	Uncoded service pack LH, non-lighted	D-42-234	Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole	D-42-235	Uncoded service pack LH, lighted keyhole	D-42-236	Use tumbler series P-42-141/145		
			Coded pair non-lighted	DP-42-134 (DWO)					
Grand Marquis (8-cut locks)	1996-11	H75	Uncoded service pack RH, non-lighted Includes pawl	D-42-253	Uncoded service pack LH, non-lighted Includes pawl	D-42-254	Use tumbler series P-42-061/065		
			Coded pair non-lighted Includes pawls R & L	DP-42-185 DL6182	Use tumbler series P-42-061/065				
LN7, Lynx	1981-87	H50	Uncoded lock chrome	D-42-231	Coded pair chrome	DL1590	Use tumbler series P-42-131/135		
			Uncoded lock black	D-42-232	Coded pair black	DP-42-148	Use tumbler series P-42-131/135		
Marauder			See Grand Marquis (2003-up) or Monterey (before 2003)						
Mariner	2005-07	H75	Replacement locks available from Ford-Lincoln-Mercury dealers only. Use tumbler series P-42-151/155						
Marquis	1970-80	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135		
Marquis	1981-86	H50	Uncoded lock	D-42-231	Coded pair	DL1590	Use tumbler series P-42-131/135		

Scroll down for more

MERCURY DOOR LOCKS

Meteor	1962-63	H27	Single lock with reversible pawl R&L	D-42-202	Use tumbler series P-42-181/185				
			Coded pair Includes pawls R & L	DP-42-103	3-piece set Ignition + 2 doors Includes pawls R & L	S-42-001			
Milan	2006-11	H75	Replacement locks available from Ford-Lincoln-Mercury dealers only. Use tumbler series P-42-151/155						
Monarch	1974-80	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135		
Montego	1968-76	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135		
Montego	2005-07	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065						
Monterey	1965-78	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135		
Monterey	2004-07	H75	Uncoded service pack	DL5885SP	Tumblers for assembly are included in the lock service pack. Pawls are not included, use P-42-322 for right side and P-42-323 for left side Face cap is available as P-42-267				
Mountaineer	1997-00	H75	Uncoded service pack Includes pawls R & L Chrome	D-42-261	Coded pair – chrome	DL5886 DP-42-180	Use face cap P-42-266 (chrome)		
			Uncoded service pack Includes pawls R & L Black	D-42-262	Coded pair – black	DL5887 DP-42-182	Use face cap P-42-265 (black)		
			SPECIAL NOTE: The uncoded locks were previously available as D-42-251 or DL5886U (chrome), and D-42-252 or DL5887U (black), which will continue to be available until stock is sold out. D-42-261 (chrome) and D-42-262 (black) uncoded service pack includes tumblers for assembly and a pawl that is reversible for right side or left side.						
Mountaineer	2001-11	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065						
Mystique (original locks made by Hurd)	1995-96	H54	Uncoded service pack RH, non-lighted	D-42-237	Uncoded service pack LH, non lighted	D-42-238	Use face cap P-42-229 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole	D-42-239	Uncoded service pack RH, lighted keyhole	D-42-240	Use face cap P-42-229 Use tumbler series P-42-141/145		
			Coded pair non-lighted	DP-42-138					
Mystique (original locks made by Valeo)	1996-1/2 to 2001	H54	Uncoded service pack RH	D-42-247	Uncoded service pack LH	D-42-248	Use face cap P-42-278 Use tumbler series P-42-141/145		
			NOTE: D-42-247 and D-42-248 are discontinued when out. The following locks can be substituted: D-42-249 for right side, D-42-250 for left side (The substitute locks also use face cap P-42-278 and tumbler series P-42-141/145)						
			NOTE TO AVOID CONFUSION: Original Valeo keys have an extra groove down the blade so it looks like an 8-cut, but otherwise it is 10-cut and all 10-cut keys without the groove can be used.						
Park Lane	1965-78	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135		
Sable	1986-93	H54	Uncoded service pack RH, non-lighted	D-42-211	Uncoded service pack LH, non-lighted	D-42-212	Use face cap right side P-42-211 Use face cap left side P-42-212 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole	D-42-213	Uncoded service pack LH, lighted keyhole	D-42-214	Use face cap right side P-42-213 Use face cap left side P-42-214 Use tumbler series P-42-141/145		
			Coded pair non-lighted	DP-42-112 DL1599					
Sable	1994-95	H54	Uncoded service pack RH, non-lighted	D-42-209	Uncoded service pack LH, non-lighted	D-42-210	Use face cap right side P-42-221 Use face cap left side P-42-222 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole	D-42-223	Uncoded service pack LH, lighted keyhole	D-42-224	Use face cap right side P-42-223 Use face cap left side P-42-224 Use tumbler series P-42-141/145		
			Coded pair non-lighted	DP-42-110					
Sable	1996-06	H75	Previously supplied as DL5883U uncoded and DL5883 coded pair, now available from Strattec						
Sable	2008-09	H75	Replacement locks available from Strattec Use tumbler series P-42-061/065						
Topaz	1984-87	H50	Uncoded lock chrome non-lighted	D-42-231	Coded pair – chrome	DL1590	Use tumbler series P-42-131/135		
			Uncoded lock black non-lighted	D-42-232	Coded pair – black	DP-42-148	Use tumbler series P-42-131/135		
			Uncoded lock with lighted keyhole (chrome only)	D-42-174	Use tumbler series P-42-131/135				
Topaz 2-door	1988-94	H54	Uncoded service pack non-lighted, chrome	D-42-221	Coded pair – chrome	DP-42-122	Use face cap P-42-201 Use tumbler series P-42-141/145		
			Uncoded service pack non-lighted, black	D-42-222	Use face cap P-42-202 Use tumbler series P-42-141/145				
			Uncoded service pack RH, lighted keyhole chrome	D-42-203	Uncoded service pack LH, lighted keyhole chrome	D-42-204	Use face cap P-42-203 Use tumbler series P-42-141/145		
			Uncoded service pack RH, lighted keyhole black	D-42-206	Uncoded service pack LH, lighted keyhole black	D-42-207	Use face cap P-42-204 Use tumbler series P-42-141/145		

Scroll down for more

MERCURY DOOR LOCKS

Topaz 4-door	1988-94	H54	Uncoded service pack RH, non-lighted	D-42-211	Uncoded service pack LH, non-lighted	D-42-212	Use face cap right side P-42-211 Use face cap left side P-42-212 Use tumbler series P-42-141/145
			Uncoded service pack RH, lighted keyhole	D-42-213	Uncoded service pack LH, lighted keyhole	D-42-214	Use face cap right side P-42-213 Use face cap left side P-42-214 Use tumbler series P-42-141/145
			Coded pair non-lighted	DP-42-112 DL1599			
Tracer	1988-90	MZ13	Coded lock with reversible pawl R&L	D-20-101	Coded pair	DP-20-101	Use face cap P-20-211 Use tumbler series P-20-111/164
Tracer (10-cut locks)	1991-11/30/95	H54	Uncoded service pack	D-42-291	Coded pair	DP-42-192	Use pawl right side P-42-315 Use pawl left side P-42-316 Use face cap P-42-202 Use tumbler series P-42-161/165
Tracer (Mazda locks)	12/1/95 - 1996	MZ19	Coded lock	D-20-110	Coded pair including pawls	DP-20-110	If original pawl cannot be reused use P-20-309 (RH) or P-20-310 (LH) Use face cap P-20-261 (black) Use tumbler series P-20-131/155
Tracer	1997-99	X221	Uncoded plug	D-20-311	Use tumbler series P-20-131/155		
Villager (station wagon)	1965-92		see Monterey, Marquis, Grand Marquis				
Villager minivan (10-cut locks)	1993-96	H54	Uncoded service pack	D-42-293	Use pawls as follows: Right side passenger door - P-42-317 Left side passenger door - P-42-318 Right side sliding lateral door - P-42-321 Use face cap P-42-202 (black) Use tumbler series P-42-161/165		
Villager minivan (8-cut locks)	1996-02	H75	Replacement locks available from Strattec Use face cap P-42-266 (chrome) or P-42-265 (black) Use tumbler series P-42-061/065				
Zephyr	1978-83	H51	Uncoded lock	D-42-201	Coded pair	DL1550	Use tumbler series P-42-131/135
Mercury Trucks (Canada)	1953-72		See Ford Pickup, Ford Van, or Ford Heavy Trucks				

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses. Some of these parts are no longer available for new purchase but are listed for the benefit of those who already have them (marked DWO / Discontinued When Out).

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Springs	Keying kits and Notes
H27 / H26	P-42-181	P-42-182	P-42-183	P-42-184	P-42-185	P-42-180	A-42-108 current keying kit – no longer available for purchase. Refill tumblers will continue to be available until sold out
H50 / H51	P-42-131	P-42-132	P-42-133	P-42-134	P-42-135	P-42-130	A-42-110 current keying kit Also contained in A-42-150 kit no longer available for purchase (DWO)
H54 (10-cut most models)	P-42-141	P-42-142	P-42-143	P-42-144	P-42-145	P-42-140	A-42-115 current keying kit Also contained in keying kits A-42-100, A-42-104, and A-42-150 keying kits no longer available for purchase (DWO)
H54 (10-cut Escort, Tracer, Villager)	P-42-161	P-42-162	P-42-163	P-42-164	P-42-165	P-42-140	Contained in keying kits A-42-100, A-42-106, and A-42-150 keying kits no longer available for purchase (DWO) Refill packs of the individual tumblers will continue to be available until sold out
H75 except below	P-42-061 RP5044	P-42-062 RP5045	P-42-063 RP5046	P-42-064 RP5047	P-42-065 RP5048	RP5043	A-42-109 keying kit (DWO) Refill packs continue to be available
H75 Mariner, Milan	P-42-151	P-42-152	P-42-153	P-42-154	P-42-155	P-42-140	A-42-113 current keying kit
HU101	P-18-151 #1L	P-18-152 #2L	P-18-153 #3L	P-18-154 #4L	P-18-155 #5L	P-31-100	A-18-111 current keying kit
	P-18-161 #1R	P-18-162 #2R	P-18-163 #3R	P-18-164 #4R	P-18-165 #5R		

Scroll down for more

MERCURY DOOR LOCKS

MZ13	P-20-111	P-20-162	P-20-163	P-20-164		P-00-100	A-20-150 current keying kit containing this and the MZ19 series Also contained in keying kit A-20-100 and A-20-101 no longer available for purchase (DWO)
MZ19	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	P-00-100	A-20-103 current keying kit containing only this series A-20-150 current keying kit containing this and the MZ13 series Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)
X21, X22							Tumblers and service parts are not available
X86 (TC code series)	P-18-111	P-18-112	P-18-113	P-18-114		P-31-100	A-18-107 current keying kit
X221	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	P-00-100	A-20-103 current keying kit containing only this series A-20-150 current keying kit containing this and the MZ13 series Also contained in keying kit A-20-100 and A-20-102 no longer available for purchase (DWO)