

OLDSMOBILE DOOR LOCKS

See the separate section for Oldsmobile before 1967 model year.

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
3. Unless specified otherwise pawls are not included with replacement locks, the original pawls must be reused.
4. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes
88	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
88	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
88	1977-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
88	1992-98	GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)	
			Uncoded service pack RH with alarm	D-41-245 (DWO)	Uncoded service pack LH with alarm	D-41-246 (DWO)	
			Plugs are available as follows Uncoded plug for locks without alarm - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315				
98	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
98	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)
98	1977-90	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201)		
			With lighted keyhole – replacement locks available from Strattec				
98	1991-96	GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)	
			Uncoded service pack RH with alarm	D-41-245 (DWO)	Uncoded service pack LH with alarm	D-41-246 (DWO)	
			Plugs are available as follows Uncoded plug for locks without alarm - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315				
442	All		see Cutlass or Cutlass Supreme (2-door)				
Achieva	1992-94	GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)	
			Plugs are available as follows Uncoded plug for locks without alarm - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315				
Achieva	1995-99	B86	Replacement locks available from Strattec				
Alero	1995-99	B99	Replacement locks available from Strattec				
Aurora	1995-99	B99	Replacement locks available from Strattec				

Scroll down for more

OLDSMOBILE DOOR LOCKS

Aurora	2001-03	B99	Uncoded service pack	D-41-005	Use tumbler series P-41-121/124 for D-41-005 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new. Use face cap P-41-205			
Bravada	1989-94	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)	
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)	
Bravada	1995-04	B97	Replacement locks available from Strattec					
Calais	1985-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Custom Cruiser Station wagon	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Custom Cruiser Station wagon	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)	
Custom Cruiser Station wagon	1977-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Custom Cruiser Station wagon	1992-96	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Cutlass Ciera	1985-96	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Cutlass	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Cutlass Salon 2-door	1980	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)	
Cutlass Salon 4-door & wagon	1979-81	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Cutlass Supreme 2-door	1979-87	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)	
Cutlass Supreme 2-door	1988-97	GMA/K	Uncoded service pack	DL1508U (DWO)	Coded pair	DL1508		
Cutlass Supreme 4-door	1979-97	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Cutlass	1997-99	B99	Replacement locks available from Strattec					
Delta 88	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Delta 88	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)	
Delta 88	1977-91	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Delta 88	1992-98	GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)		
			Uncoded service pack RH with alarm	D-41-245 (DWO)	Uncoded service pack LH with alarm	D-41-246 (DWO)		
			Plugs are available as follows Uncoded plug for locks without alarm - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315					
F-85	1967-75	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Firenza	1982-88	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Intrigue	1998-02	B99	Replacement locks available from Strattec					
Ninety Eight	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Ninety Eight	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)	
Ninety Eight	1977-90	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201)			
			With lighted keyhole – replacement locks available from Strattec					
Ninety Eight	1991-96	GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)		
			Uncoded service pack RH with alarm	D-41-245 (DWO)	Uncoded service pack LH with alarm	D-41-246 (DWO)		
			Plugs are available as follows Uncoded plug for locks without alarm - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315					
Omega	1973-84	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Regency	all		see 98 / Ninety Eight					
Royale	all		see 88 / Delta 88					
Silhouette	1990-96	GMA/K	Uncoded service pack without factory alarm or automatic locking 1990-96	D-41-203 (chrome) D-41-249 (black)	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202)			
			Uncoded service pack with factory alarm or automatic locking (1991-96 only)	D-41-216 (chrome) D-41-250 (black)	NOTE: D-41-216 uses H keyway used on 1991-96 models only. Uncoded service package not available with other keyways as used 1990 Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202)			
Silhouette	1997-04	B97	Replacement locks available from Strattec					
Starfire	1975-80	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	

Scroll down for more

OLDSMOBILE DOOR LOCKS

Toronado, Trofeo	1968-92	GMA/K	Uncoded service pack no alarm, non lighted	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
			Coded pair with factory alarm no lighted keyhole	DP-41-115	Use face cap RP6036 (P-41-201)			
			Uncoded service pack with factory alarm no lighted keyhole	D-41-215	NOTE: D-41-215 uses H keyway used on 1991-92 models only. Uncoded service package not available with other keyways as used 1968-90 Use face cap RP6036 (P-41-201)			
			With lighted keyhole – replacement locks available from Strattec					

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B85, B89, B97, B99 Locks made by Lockcraft and Strattec	P-41-161 RP6420 322241	P-41-162 RP6421 322242	P-41-163 RP6422 322243	P-41-164 RP6423 322244		A-41-102 keying kit supplied by ASP which is no longer available for purchase Also contained in keying kit SK6400 which is no longer available for purchase
B85, B89, B97, B99 Locks made by Ortech	P-41-121	P-41-122	P-41-123	P-41-124		A-41-104 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B85, B89, B97, B99 Locks made by HUF	P-41-111	P-41-112	P-41-113	P-41-114		A-41-103 current keying kit Also contained in keying kit A-41-150 which is no longer available for purchase
B102, B107, B111 Locks made by Ortech	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	Contained in keying kit A-41-152 which is no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107, B111 Locks made by Strattec						These tumblers are only available from Strattec, several different designs are used, check according to the exact year and model application that you are working on.
GMA through GMK (single sided keys, sidebar locks)	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP

Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (previously RP6157 or RP6043)

For locks using double bitted keys B97, etc. - part no. RP6419