See the separate section for Pontiac before 1967 model year.

General information as follows:

- 1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
- 2. Unless specified otherwise all locks using single sided keys GM-A through GM-K have universal groove that will accept all 8 keyway variations. These locks will not accept the pre-1967 B10/B11 keys.
- 3. Unless specified otherwise pawls are not included with replacement locks, the original pawls must be reused.
- 4. Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes				
1000	1981-87	GMA/K	see T1000								
6000	1092.01	0144/46	Uncoded service pack (chrome)			DL1580	Use face cap RP6036 (P-41-201)				
6000	1983-91 GMA/K		Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)				
Acadian	1982-87	GMA/K	Uncoded service pack (chrome) DL1580U		Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)				
Acadian	1902-07	GIVIA/K	Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)				
Astre	1971-77	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)				
Aztek	2001-05	B99	Replacement locks available from Pontiac / GM dealers only. Face cap must be removed to service original lock on the car, replacement caps not currently available Use tumbler series P-41-111/114								
Bonneville	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)				
Bonneville	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)				
		1 GMA/K	Uncoded service pack no alarm, non lighted chrome	DL1580U	Coded pair no alarm, non lighted chrome	DL1580	Use face cap RP6036 (P-41-201)				
			Uncoded service pack no alarm, non lighted black	DL1525U Coded pair no alarm, non lighted black		DL1525	Use face cap RP6520 (P-41-202)				
Bonneville	1977-91		Uncoded service pack with factory alarm no lighted keyhole chrome	D-41-215	Uncoded service pack with factory alarm no lighted keyhole black	D-41-242	NOTE: D-41-215 and D-41-242 use H keyway used 1991 only. Uncoded service package not available with other keyways as used 1977-90 Use face caps: Chrome: RP6036 (P-41-201) Black: RP6520 (P-41-202)				
			Coded pair with factory alarm no lighted keyhole chrome	DP-41-115	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6520 (P-41-202)						
			With lighted keyhole - re	With lighted keyhole – replacement locks available from Strattec							

			Uncoded service pack	D-41-243	Uncoded service pack	D-41-244				
		GMA/K	RH no alarm	(DWO)	LH no alarm	(DWO)				
Bonneville	4000 00		Uncoded service pack RH with alarm	D-41-245 (DWO)	Uncoded service pack LH with alarm	D-41-246 (DWO)				
Doffileville	1992-99		Plugs are available as follows Uncoded plug for locks without alarm, unrestricted keyway accepts all GMA through GMK - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315							
Bonneville	2000-05	B99	Uncoded service pack	D-41-005	Use tumbler series P-41-121/124 for D-41-005 sold by ASP. Different tumblers may be used for locks not sold by ASP including some locks sold by GM dealers or originally installed on the car when it was new.		d by ASP including some locks sold			
Catalina & Executive	1967-70	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)			
Catalina & Executive	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)			
			Uncoded service pack no alarm, non lighted chrome	DL1580U	Coded pair no alarm, non lighted DL1580 chrome		Use face cap RP6036 (P-41-201)			
			Uncoded service pack no alarm, non lighted black	DL1525U	Coded pair no alarm, non lighted black	DL1525	Use face cap RP6520 (P-41-202)			
Catalina & Executive	1977-81	GMA/K	Uncoded service pack with factory alarm no lighted keyhole chrome	D-41-215	Uncoded service pack with factory alarm no lighted keyhole black	D-41-242	NOTE: D-41-215 and D-41-242 use H keyway used 1991 only. Uncoded service package not available with other keyways as used 1977-90 Use face caps: Chrome: RP6036 (P-41-201) Black: RP6520 (P-41-202)			
			Coded pair with factory alarm no lighted keyhole chrome	DP-41-115	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6520 (P-41-202)					
	1001.00	0144/1/	• •	•	cks available from Strattec					
Fiero	1984-89	GMA/K	Replacement locks avail Uncoded service pack			l	T			
Firebird 196	1967-92	GMA/K	(chrome) Uncoded service pack	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)			
			(black) Uncoded service pack	DL1525U D-41-214	Coded pair (black)	DL1525 DL6553	Use face cap RP6520 (P-41-202)			
Firebird 19	1993-02	GMA/K	(black) Uncoded service pack	D-41-214	Coded pair (black)	(DWO) DL6943	Use face cap RP6520 (P-41-202)			
			(chrome)	D-41-247	Coded pair (chrome)	(DWO)	Use face cap RP6036 (P-41-201) Use face cap P-24-203 (old part no.			
Firefly	1985-88	DC1	Complete lock with reversible pawl	D-33-101	Coded pair with pawls	DP-33-101	P-30-202). Use tumbler series P-30-141/144			
Firefly	1989-94	B65	Uncoded service pack	D-33-205	Use tumbler series P-30-	reused, use 1 161/164	P-33-301 (RH) or P-33-302 (LH)			
Firefly	1995-97	B65	Coded lock (no pawl)	D-33-207 Previously sold as D-33-107 (RH) and D-33-108 (LH) If the original pawl cannot be reused, use P-33-303 (RH) or P-33-304 (LI Use face cap P-30-217 Use tumbler series P-30-161/164						
Firefly	1998-01	B69	Uncoded service pack	D-33-204	Original pawls must be re Use face cap P-20-265 Use tumbler series P-20-	eused.				
G3 hatchback	2004-11	DWO4R	Complete lock RH	D-50-115	Complete lock LH	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)			
G3 sedan	2004-06	DWO4R	Complete lock RH	D-50-115	Complete lock LH	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)			
G3 sedan	2007-11	DWO4R	Complete lock RH	D-50-117	Complete lock LH	D-50-118	Use tumbler series P-13-101/104 (P-21-111/114)			
G5	2005-10	B111	Coded lock	D-41-006	Includes extra tumblers f without destroying it.	, ,	The face cap can be removed			
G6	2005-08	B111	Uncoded service pack	D-41-003		r locks not sol	I-41-003 sold by ASP. Different d by ASP including some locks sold in the car when it was new.			
G8	2008-09	GM45P	Replacement locks avai	lable from Pon		1				
Grand Am	1985-91	I GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)			
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)			
		4 GMA/K	Uncoded service pack RH no alarm	D-41-243 (DWO)	Uncoded service pack LH no alarm	D-41-244 (DWO)				
Grand Am	1992-94		Plugs are available as follows Uncoded plug for locks without alarm, unrestricted keyway accepts all GMA through GMK - D-41-301 Uncoded plug for locks with alarm (available only with restricted H keyway) - D-41-302 Coded pair of plugs - DP-41-315							

Grand Am	1005.00	D07	Replacement locks available from Strattec						
Grand Am	1995-06	B97		1	1	DI 4500	Has fore our DDCCCC (D. 44, CC4)		
Grand Prix	1967-78	GMA/K	Uncoded service pack Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
Grand Prix	1979-87	GMA/K	(chrome) Uncoded service pack	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201)		
			(black)	DL1527U	Coded pair (black)	DL1527	Use face cap RP6520 (P-41-202)		
Grand Prix 2-dr	1988-96	GMA/K	Uncoded service pack	DL1508U (DWO)	Coded pair	DL1508			
Grand Prix 4-dr	1990-96	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)		
			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)		
Grand Prix	1997-03	B99	Replacement locks avai	Replacement locks available from Strattec					
Grand Prix	2004-08	B111	Uncoded service pack D-41-004 (DWO) Use tumbler series P-41-021/024 for D-41-004 sold by ASP. tumblers may be used for locks not sold by ASP including some by GM dealers or originally installed on the car when it was new				ld by ASP including some locks sold		
Grand Ville	1971-76	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)		
GT-37	1971	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
GTO	1967-74	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
GTO	2004-06	HU43	Uncoded plug	D-23-312		available – pa	rt no. MP-23-110, contains enough east one lock with some left over.		
J2000	1982-86	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)		
J2000	1302-00	GIVIAVK	Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)		
Laurentian	1967-83		see Bonneville						
Lemans	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
Lemans 2-door	1979-81	GMA/K	Uncoded service pack	DL1582U	Coded pair	DL1582	Use face cap RP6036 (P-41-201)		
Lemans 4-door	1979-81	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
Lemans	1988-92	B61	Uncoded service pack including pawl (R&L) D-23-208 Plastic pawl retainer: P-23-241 (included with D-23-208, avaise separately to service original lock, usually destroyed when distributed by the control of the contr						
Montana	1997-05	B97	Replacement locks available from Strattec Use tumbler series P-41-161/164						
	2005-07	B107 or	Locks using B107 keys, available from Pontiac / GM dealers only.						
Montana			Use tumbler series P-41-011/015 Locks using B86 keys, available from Strattec						
		B86	Use tumbler series P-41		Strattec				
Parisienne	1968-83		see Bonneville						
Parisienne	1984-89	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
Phoenix	1978-84	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201		
Pursuit	2005-10	B111	Coded lock D-41-006		Includes extra tumblers for rekeying. The face cap can be removed without destroying it.				
Safari wagon	1968-91		see Bonneville	•	,				
Solstice	2005-10	B111	Coded lock	D-41-006	Includes extra tumblers for rekeying. without destroying it.		The face cap can be removed		
Sunbird	1979-94	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
Sunburst	1985-91	B53	Uncoded service pack without pawl	D-24-202	Uncoded plug	D-24-302	Use face cap P-30-271 (chrome) or P-30-215 (black) Use tumbler series P-24-101/104		
Sunfire	1995-05	B97	Replacement locks avail Use face cap RP6036 (F Use tumbler series P-41	P-41-201) chro	ttec me, or RP6520 (P-41-202)	black			
Sunrunner	1989-98	B69	Coded lock without pawl	D-33-203	If original pawl cannot be Use face cap P-33-201 Use tumbler series P-20-		P-30-322 (RH) or P-30-323 (LH)		
T-37	1971	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
			Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)		
T1000	1982-87	87 GMA/K	Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)		
Tempest	1967-71	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)		
·	1987 to 1988 mid-	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)		
Tempest (Canada and			Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)		
export)	year			ar change in 1	988 from the short plug to	the medium p	lug		
Tompost	Mid-		and ye		l l l l l l l l l l l l l l l l l l l		<u>- </u>		
Tempest (Canada and export)	year 1998 To 1991	GMA/K	Uncoded service pack (chrome)	DL1582U	Coded pair (chrome)	DL1582	Use face cap RP6036 (P-41-201)		
Torrent	2006	B99	Replacement locks avail Use tumbler series P-41				•		
			1 230 (02.3) 0011001 71	,	•				

Torrent	2007-08	B111	Uncoded service pack	D-41-003		r locks not so	0-41-003 sold by ASP. Different Id by ASP including some locks sold in the car when it was new.	
Trans Am	s Am 1967-92	GMA/K	Uncoded service pack (chrome)	DL1580U	Coded pair (chrome)	DL1580	Use face cap RP6036 (P-41-201)	
ITAIIS AIII	1967-92	GIVIA/K	Uncoded service pack (black)	DL1525U	Coded pair (black)	DL1525	Use face cap RP6520 (P-41-202)	
Trans Am	1993-02	GMA/K	Uncoded service pack (black)	D-41-214	Coded pair (black)	DL6553 (DWO)	Use face cap RP6520 (P-41-202)	
Trans Am	1993-02	GINIA/K	Uncoded service pack (chrome)	D-41-247	Coded pair (chrome)	DL6943 (DWO)	Use face cap RP6036 (P-41-201)	
Trans Sport 1990-96 GMA/K GMA/K Without factory or automatic lo 1990-96 Uncoded servi with factory ale automatic locki		CNAA/IV	Uncoded service pack without factory alarm or automatic locking 1990-96	D-41-203 (chrome) D-41-249 (black)	Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202)			
		Uncoded service pack with factory alarm or automatic locking (1991-96 only)	D-41-216 (chrome) D-41-250 (black)	NOTE: D-41-216 uses H keyway used on 1991-96 models only. Uncoded service package not available with other keyways as used 1990 Use chrome face cap RP6036 (P-41-201) Use black face cap RP6045 (P-41-202)				
Trans Sport	1997-05	B97	Replacement locks available from Strattec Use tumbler series P-41-161/164					
Ventura	1967-78	GMA/K	Uncoded service pack	DL1580U	Coded pair	DL1580	Use face cap RP6036 (P-41-201)	
Vibe	2003-07	TR47 10-cut	If the original shaft (pawl) can be reused, the following locks can be used: D-30-529 for right side D-30-530 for left side Complete locks including shaft (pawl) are available from GM or Toyota dealers only Use face cap P-30-268 Use tumbler series P-30-131/134					
Wave hatchback	2004-08	DWO4R	Complete lock RH	D-50-115	Complete lock LH	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)	
Wave sedan	2004-06	DWO4R	Complete lock RH	D-50-115	Complete lock LH	D-50-116	Use tumbler series P-13-101/104 (P-21-111/114)	
Wave sedan	2007-08	DWO4R	Complete lock RH	D-50-117	Complete lock LH	D-50-118	Use tumbler series P-13-101/104 (P-21-111/114)	

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

General Motors is different from most other car manufacturers because locks using the same keyway may use different tumblers depending upon who manufactured the lock and in some cases when it was manufactured. Also some replacement locks may use tumblers different from the lock installed on the car when it was built and which are not available from any known source. As such these tumbler references are correct only to the extent of information that is available to us.

To help avoid confusion, whenever possible the year and model section includes which tumbler series to use in the notes section.

Key Blank	Tumbler #1 depth	Tumbler #2 depth	Tumbler #3 depth	Tumbler #4 depth	Tumbler #5 depth	Keying kits and Notes
B10, B11	P-41-101 RP6038 322051	P-41-102 RP6039 322052	P-41-103 RP6040 322053	P-41-104 RP6041 322054	P-41-105 RP6042 322055	SK6035 keying kit supplied by ASP
B53, B57	P-24-101	P-24-102 (DWO)	P-24-103	P-24-104 (DWO)		Contained in A-24-101 and A-30-150 keying kits which are no longer available for purchase. Refill packs of the individual tumblers will continue to be available until sold out.
B54	P-16-161	P-16-162	P-16-163	P-16-164		A-16-106 current keying kit Also contained in the A-16-100 and A-16-101 keying kits which are no longer available for purchase.

	T	ı	1	T	ı	
						A-13-101 current keying kit for this series only
	P-13-101	P-13-102	P-13-103	P-13-104		Also contained in the A-21-101 current keying kit
B61	Or	Or	Or	Or		Also contained in the A-41-152 keying kit which is no longer
	P-21-111	P-21-112	P-21-113	P-21-114		available for purchase.
						Refill packs may be ordered under the P-13-101/104 or
						P-21-111/114 part numbers, same parts at the same price. A-30-106 current keying kit
B65	P-30-161	P-30-162	P-30-163	P-30-164		, ,
						Also contained in the A-30-150 keying kit which is no longer available for purchase.
						A-20-103 current keying kit containing only this series
						A-20-150 current keying kit containing this and the MZ13
B69	P-20-131	P-20-132	P-20-133	P-20-144	P-20-155	series
						Also contained in keying kit A-20-100 and A-20-102 no longer
B85, B89,						available for purchase (DWO)
B97, B99	P-41-161	P-41-162	P-41-163	P-41-164		A-41-102 keying kit assembled by ASP (DWO) SK6400 keying kit assembled by Lockcraft (DWO)
Locks made by Lockcraft	RP6420 322241	RP6421 322242	RP6422 322243	RP6423 322244		Refill parts will be available until sold out, tumblers made by
and Strattec						Strattec will also work in these locks.
B85, B89, B97, B99						A-41-104 current keying kit
Locks made by Ortech sold	P-41-121	P-41-122	P-41-123	P-41-124		Also contained in keying kit A-41-150 which is no longer
by ASP						available for purchase
B85. B89, B97. B99						A-41-103 current keying kit
Locks made	P-41-111	P-41-112	P-41-113	P-41-114		Also contained in keying kit A-41-150 which is no longer
by HUF B102, B107,						available for purchase
B111 Locks						Contained in keying kit A-41-152 which is no longer available
made by Ortech sold by	P-41-011	P-41-012	P-41-013	P-41-014	P-41-015	for purchase.
ASP – except						Refill packs of the individual tumblers will continue to be
Grand Prix (see below)						available until sold out.
B102, B107,						Contained in keying kit A-41-152 which is no longer available for purchase.
B111 Locks for Grand Prix	P-41-021	P-41-022	P-41-023	P-41-024		·
doors only						Refill packs of the individual tumblers will continue to be available until sold out.
B102, B107,						These tumblers are only available from Strattec, several
B111 Locks made by						different designs are used, check according to the exact year
Strattec						and model application that you are working on.
DC1, DC3	P-30-141	P-30-142	P-30-143	P-30-144		A-30-116 current keying kit
DC1, DC3	P-30-141	P-30-142	P-30-143	P-30-144		Also contained in the A-30-104 and A-30-150 keying kits
						which are no longer available for purchase. A-13-101 current keying kit for this series only
						Also contained in the A-21-101 keying kit
DWO4R	P-13-101	P-13-102	P-13-103	P-13-104		. ,
DWO4C (DWO4CT6)	Or P-21-111	Or P-21-112	Or P-21-113	Or P-21-114		Also contained in the A-41-152 keying kit which is no longer available for purchase.
						·
						Refill packs may be ordered under the P-13-101/104 or P-21-111/114 part numbers, same parts at the same price.
GMA through	P-41-101	P-41-102	P-41-103	P-41-104	P-41-105	
GMK (single sided keys,	RP6038 322051	RP6039 322052	RP6040 322053	RP6041 322054	RP6042 322055	SK6035 keying kit supplied by ASP
sidebar locks) GM45P	322031	322032	322033	322034	322000	Tumblers and service parts are not available
JIVITOI	P-23-111	P-23-112	P-23-113	P-23-114	P-23-115	A-23-102 current full size keying kit
HU43	(#1 depth)	(#2 depth	(#3 depth	(#4 depth	(#5 depth	Mini-pack of tumblers is also available as part no. MP-23-110
1.10-30	P-23-116 (#6 depth)	P-23-117 (#7 depth	P-23-118 (#8 depth	P-23-119 (#9 depth		Contains enough tumblers and springs to assemble at least
TR47 10-cut	P-30-131	P-30-132	P-30-133	P-30-134		one lock with some left over. A-30-113 current keying kit
11X47 10-CUL	1-00-101	1 -00-102	1 -00-100	1-00-104	1	A 30 TT3 Guitetit keying kit

Scroll down for information about tumbler springs

Tumbler springs:

For sidebar locks using single bitted keys B10, B11, GMA/GMK - part no. P-41-100 (previously RP6157 or RP6043).

For locks using double bitted keys B97, etc. - part no. RP6419

For locks using B61, DWO4R, DWO4C keys - part no. P-31-100

For locks using HU43 2-track high security keys - part no. P-31-100

For locks using TR47, B110, DA34, DC1, TR33, and other similar keys (Japanese design locks) P-00-100 - currently active part number - 100 springs per pack
This spring can also be substituted to use in locks using double bitted keys B97, etc.:

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
D 20 40F	

P-30-105