# **SCION LOCKS**

#### General information as follows:

- 1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
- 2. Locks are only available coded with keys.
- 3. Identify which tumblers and keying kits to use according to the separate chart organized by the key blank numbers.

#### **Ignition Locks**

Model	Years	Key	Part description	Part no.	Notes	
FR-S	2013-16	TR47 10-cut	Coded cylinder	C-30-198		
iA	2016		Pushbutton start only			
iM	2016	TOY48	Coded cylinder	C-30-509		
iQ	2012-15	TR47 10-cut	Coded cylinder	C-30-173		
TC	2005-10	TR47 10-cut	Coded cylinder	C-30-180		
TC	2011-16	TR47 10-cut	Coded cylinder	C-30-198		
TC - 10 <sup>th</sup> Anniversary (high security)	2013	TOY48	Coded cylinder	C-30-509		
XA	2004-06	TR47 10-cut	Coded cylinder	C-30-175		
ХВ	2004-06	TR47 10-cut	Coded cylinder	C-30-175		
		TR47 10-cut	Coded cylinder (normal key, as used on most models)	C-30-199		
XB	2008-16	TOY48	Coded cylinder Using TOY48 high security key	C-30-509		
		The lock wit	he lock with TOY48 high security key is used on special edition limited edition models only.			
XD	2008-14	TR47 10-cut	Coded cylinder	C-30-199		

#### **Door Locks**

Remember: Right side (RH) is the Passenger Side, Left side (LH) is the Driver Side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes		
FD 0	2013-16	TR47 10-cut	no lock cylinder on RH side		Complete lock LH	D-30-580	Use face cap P-30-268		
rk-5	FR-S 2013-16	80000 series	For cars with pushbutton start Replacement locks available from Scion / Toyota dealers only						
iA	2016	MZ31	Replacement locks available from Scion / Toyota dealers only						
iM	2016	TOY48	Replacement locks available from Scion / Toyota dealers only						
iQ	2012-15	TR47 10-cut	Replacement locks available from Scion / Toyota dealers only						
iQ electric	2013	TOY48	For cars with pushbutton start Replacement locks available from Scion / Toyota dealers only						
TC	2005-10	TR47 10-cut	Complete lock RH	D-30-541	Complete lock LH	D-30-542	Use face cap P-30-268		

Scroll down for more

# **SCION LOCKS**

тс	2011-16	TR47 10-cut	For cars with mechanical ignition lock Replacement locks available from Scion / Toyota dealers only					
		TOY48	For cars with pushbutton start Replacement locks available from Scion / Toyota dealers only					
XA	2004.00	TR47	Complete lock RH	D-30-535	Complete lock LH	D-30-536	Use face cap P-30-268	
XA	2004-06	10-cut	NOTE D-30-535 can be replaced by D-30-557, D-30-536 can be replaced by D-30-558					
ХВ	2004-06	TR47 10-cut	Complete lock RH	D-30-537	Complete lock LH	D-30-538	Use face cap P-30-265	
ХВ	2008-16	TR47 10-cut	no lock cylinder on RH side Complete lock LH D-30-544 Use face cap P-30-268				Use face cap P-30-268	
		TOY48	For special limited edition models only Replacement locks available from Scion / Toyota dealers only					
XD	2008-14	TR47 10-cut	no lock cylinder on RH side		Complete lock LH	D-30-560	Use face cap P-30-268	

### Rear compartment locks

Model	Years	Key	Part description	Part no.	Notes
XA	2004-06	TR47 10-cut	Complete lock	B-30-564	
Other Scion models have only remote release for the rear compartment, no lock cylinders.					

#### Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses.

Key Blank	Tumbler	Tumbler	Tumbler	Tumbler	Keying kits and Notes
MZ31					Try the Mazda tumblers in A-20-103 keying kit, this has not been verified to work on the Scion versions.
TR47 10-cut (no split tumblers)	#1 depth P-30-131	#2 depth P-30-132	#3 depth P-30-133	#4 depth P-30-134	A-30-113 keying kit. This is the 50000-69999 code series, also known as TR47 10-cut design, without split tumblers.
TOY48 "Lexus short key"	#1 depth split P-30-121	#2 depth split P-30-122	#3 depth split P-30-123	#2 depth alternate split P-30-124	A-30-115 keying kit  Also note that some code listings use depths 1,3,5 instead of 1,2,3. In that case our #2 is their #3, and our #3 is their #5  The no. 2 alternate is used when necessary, if the P-30-122 does not work in a particular chamber use the P-30-124.
80000 code series	Y depth P-30-711	S depth P-30-712	N depth P-30-713	I depth P-30-714	A-30-118 keying kit.

# Tumbler springs:

Over the years we have sold tumbler springs under several different part numbers. As there are very minor differences between the springs used in most Japanese and Korean locks, we have consolidated the various springs as follows:

P-00-100 - currently active part number - 100 springs per pack

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
P-30-105	